Annual Report to the North Carolina General Assembly

Status Report on Individually Permitted Discharging Systems

July 1, 2017 - June 30, 2018

Division of Water Resources



NORTH CAROLINA DEPARTMENT OF ENVIRONMENTAL QUALITY

Summary

North Carolina General Statute (N.C.G.S.) 143-215.9A requires the Department of Environmental Quality to report to the Environmental Review Commission and the Fiscal Research Division on the status of facilities discharging into surface waters during the previous fiscal year. Facilities discharging into surface waters are required by N.C.G.S. 143-215.1 to first apply for and secure a permit from the Environmental Management Commission. As a result, the data provided within this fiscal report is captured for those facilities individually permitted with National Pollutant Discharge Elimination System (NPDES) permits.

The enclosed report details the inspections completed and the enforcement actions taken in North Carolina during fiscal year 2017-2018 by the Division of Water Resources. In addition, information on Special Orders by Consent is included. The report also includes a table showing the number of permits issued by region and the names and locations of the individually permitted discharging facilities.

The enclosed tables list totals for each of the department's regional offices as well as state totals. The regional offices are noted as follows:

- ◆ ARO Asheville Regional Office
- ◆ FRO Fayetteville Regional Office
- ♦ MRO Mooresville Regional Office
- ♦ RRO Raleigh Regional Office
- ♦ WARO Washington Regional Office
- ♦ WIRO Wilmington Regional Office
- ♦ WSRO Winston-Salem Regional Office

If any additional information or clarification is needed, please contact Brianna Young at 919-707-3619.



CONTENTS

Table 1	Enforcement actions taken, civil penalties assessed and collected, and remissions requested July 1, 2017 through June 30, 2018
Table 2	Permits issued and inspections completed July 1, 2017 through June 30, 2018
Table 3	Special Orders by Consent active and pending July 1, 2017 through June 30, 2018
Table 4	Names and locations of individually permitted discharging facilities as of Aug. 1, 2018
Table 5	Violations broken down individually by inspection
Addendum	Support information



ADDENDUM

The following is provided to support the information in the above status report.

- As found in Table 1, "Other Permit Condition Violations" may include
 - □ Discharge violations (resulting from collection system overflows)
 - □ Submitting late discharge monitoring reports
 - □ Submitting late toxicity tests
 - □ Permit condition violations (for example, violations of a pre-treatment program, improper operation and maintenance of treatment works, or by-pass of treatment works)
- As found in Table 2, "Other Inspections" include:
 - □ **Audit Inspections**: A comprehensive review of all elements of a municipal's pretreatment program including a records review and an inspection of an industrial facility conducted once every five years.
 - □ **Bioassay Compliance Inspections**: Evaluates the biological effect of a permittee's effluent discharge on test organisms using acute and chronic toxicity testing.
 - □ Compliance Sampling Inspections (CSI): A sampling inspection designed to verify the permittee's compliance with applicable permit self-monitoring requirements. Analytical results from representative samples collected during the inspection are used to evaluate the permittee's compliance.
 - □ **Diagnostic Inspections**: An inspection that focuses on publicly owned treatment works that have not achieved permit compliance. The purpose is to identify the causes of noncompliance, suggest immediate remedies and support current or future enforcement action.
 - □ **Operation & Maintenance Inspections**: An inspection that focuses on the operation and maintenance aspect of a facility.
 - □ **Performance Audit Inspections**: Inspections that include actual observation of the permittee performing the self-monitoring process from sample collection and flow measurements through laboratory analyses, data work-up and reporting.
 - □ **Pre-Treatment Inspections**: An annual inspection of a municipal's pretreatment program.
 - □ **Toxicity Sampling Inspections**: The same as the Compliance Sampling Inspections mentioned above, however, increased emphasis is placed on toxic substances regulated by the National Pollution Discharge Elimination System (NPDES) permit.
- Effective July 1, 1998, the director of the then Division of Water Quality delegated each regional water quality supervisor the authority to sign all civil penalty assessments for fast-track enforcement actions for violations of NPDES permit effluent limits and/or monitoring frequencies in accordance with N.C. General Statute 143-215.6A.
- Due to the length of the post assessment process, total civil penalties assessed and total civil penalties collected will not coincide.



Table 5. Violations listed by Inspection

REGION	PERMIT NUMBER	-	FACILITY NAME	OWNER NAME	COUNTY	INSPECTION DATE	COMPLIANCE STATUS	VIOLATION DATE	VIOLATION CATEGORY	VIOLATION AREA	VIOLATION TYPE
Asheville	NC0000353	4	The Feldspar Corporation	The Quartz Corp USA	Mitchell	02/07/2018	Not Compliant	02/07/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0000353	4	The Feldspar Corporation	The Quartz Corp USA	Mitchell	02/07/2018	Not Compliant	02/07/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0000353	4	The Feldspar Corporation	The Quartz Corp USA	Mitchell	02/07/2018	Not Compliant	02/07/2018	Other Violation	Violation detected during inspection	Permit
Asheville	NC0000353	4	The Feldspar Corporation	The Quartz Corp USA	Mitchell	02/07/2018	Not Compliant	02/07/2018	Other Violation	Violation detected during inspection	Pump Station - Influent
Asheville	NC0000353	4	The Feldspar Corporation	The Quartz Corp USA	Mitchell	02/07/2018	Not Compliant	02/07/2018	Other Violation	Violation detected during inspection	Record Keeping
Asheville	NC0000353	4	The Feldspar Corporation	The Quartz Corp USA	Mitchell	02/07/2018	Not Compliant	02/07/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Asheville	NC0000353	4	The Feldspar Corporation	The Quartz Corp USA	Mitchell	02/07/2018	Not Compliant	02/07/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Raleigh	NC0001376	2	Riverplace WWTP	Riverplace IV LLC	Wake	12/07/2017	Not Compliant	12/07/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Raleigh	NC0001376	2	Riverplace WWTP	Riverplace IV LLC	Wake	12/07/2017	Not Compliant	12/07/2017	Other Violation	Violation detected during inspection	Permit
Raleigh	NC0001376	2	Riverplace WWTP	Riverplace IV LLC	Wake	12/07/2017	Not Compliant	12/07/2017	Other Violation	Violation detected during inspection	Permit
Raleigh	NC0001376	2	Riverplace WWTP	Riverplace IV LLC	Wake	12/07/2017	Not Compliant	12/07/2017	Other Violation	Violation detected during inspection	Permit
Raleigh	NC0001376	2	Riverplace WWTP	Riverplace IV LLC	Wake	12/07/2017	Not Compliant	12/07/2017	Other Violation	Violation detected during inspection	Permit
Raleigh	NC0001376	2	Riverplace WWTP	Riverplace IV LLC	Wake	12/07/2017	Not Compliant	12/07/2017		Violation detected during inspection	Permit
J			·	·			·			Ğ İ	
Winston-Salem	NC0001643	5	MGM Transport WWTP	Eden Real Estate	Rockingham	07/17/2017	Not Compliant	07/17/2017	Other Violation	Violation detected during inspection	Record Keeping
Winston-Salem	NC0001643	5	MGM Transport WWTP	Associates LLC Eden Real Estate Associates LLC	Rockingham	07/17/2017	Not Compliant	07/17/2017	Other Violation	Violation detected during inspection	Secondary Clarifier
Fayetteville	NC0003573	4	Chemours Company- Fayetteville Works	The Chemours Company Fc	Bladen	11/03/2017	Not Compliant	11/03/2017	Other Violation	Discharge without valid permit	Permit
Fayetteville	NC0003573	4	Chemours Company-	The Chemours Company Fc	Bladen	11/03/2017	Not Compliant	04/20/2018	Other Violation	Stream Standards violation	Permit
Asheville	NC0004464	4	Fayetteville Works Woodland Mills WWTP	LLC Polk County	Polk	02/12/2018	Not Compliant	02/12/2018	Other Violation	Violation detected during inspection	Permit
Mooresville	NC0004812	5	Pharr Yarns Industrial WWTP	Pharr Yarns Inc	Gaston	04/11/2018	Not Compliant	04/11/2018	Other Violation	Violation detected during inspection	Aeration Basins
Mooresville	NC0004812	5	Pharr Yarns Industrial WWTP	Pharr Yarns Inc	Gaston	04/11/2018	Not Compliant	04/11/2018	Other Violation	Violation detected during inspection	Effluent Sampling
Mooresville	NC0004812	5	Pharr Yarns Industrial WWTP	Pharr Yarns Inc	Gaston	04/11/2018	Not Compliant	04/11/2018	Other Violation	Violation detected during inspection	Flow Measurement - Effluent
Mooresville	NC0004812	5	Pharr Yarns Industrial WWTP	Pharr Yarns Inc	Gaston	04/11/2018	Not Compliant	04/11/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Mooresville	NC0004812	5	Pharr Yarns Industrial WWTP	Pharr Yarns Inc	Gaston	04/11/2018	Not Compliant	04/11/2018	Other Violation	Violation detected during inspection	Record Keeping
Mooresville	NC0004812	5	Pharr Yarns Industrial WWTP	Pharr Yarns Inc	Gaston	04/11/2018	Not Compliant	04/11/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Mooresville	NC0006190	4	South Fork Industries - Maiden Plant	South Fork Industries Inc	Catawba	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Aeration Basins
Mooresville	NC0006190	4	South Fork Industries - Maiden Plant	South Fork Industries Inc	Catawba	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Bar Screens
Mooresville	NC0006190	4	South Fork Industries - Maiden Plant	South Fork Industries Inc	Catawba	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Influent Sampling
Mooresville	NC0006190	4	South Fork Industries - Maiden Plant	South Fork Industries Inc	Catawba	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Laboratory

Mooresville	NC0006190	4	South Fork Industries - Maiden	South Fork Industries Inc	Catawba	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Mooresville	NC0006190	4	Plant South Fork Industries - Maiden	South Fork Industries Inc	Catawba	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Records/Reports
			Plant								
Mooresville	NC0006190	4	South Fork Industries - Maiden	South Fork Industries Inc	Catawba	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Mooresville	NC0020052	4	Plant McAdenville WWTP	Town of McAdenville	Gaston	07/05/2017	Compliant	07/05/2017	Other Violation	Violation detected during inspection	Effluent Sampling
.viooresviiie	1100020032	·	mo dentine trans	Town of Moracentine	Caston	0,,03,201,	Compilant	07,03,2027	other violation	violation detected daring inspection	Emacin sumpling
Mooresville	NC0020052	4	McAdenville WWTP	Town of McAdenville	Gaston	07/05/2017	Compliant	07/05/2017	Other Violation	Violation detected during inspection	Influent Sampling
Raleigh	NC0020389	4	Benson WWTP	Town of Benson	Johnston	06/21/2018	Not Compliant	06/21/2018	Other Violation	Violation detected during inspection	Effluent Sampling
Raleigh	NC0020389	4	Benson WWTP	Town of Benson	Johnston	06/21/2018	Not Compliant	06/21/2018		Violation detected during inspection	Influent Sampling
Raleigh	NC0020389	4	Benson WWTP	Town of Benson	Johnston	06/21/2018	Not Compliant	06/21/2018		Violation detected during inspection	Operations & Maintenance
Naieigii	140020383	4	DETISOTI VV VV IF	TOWIT OF BEHSON	Johnston	00/21/2018	Not Compilant	00/21/2018	Other violation	violation detected during inspection	Operations & Maintenance
Raleigh	NC0020389	4	Benson WWTP	Town of Benson	Johnston	06/21/2018	Not Compliant	06/21/2018	Other Violation	Violation detected during inspection	Record Keeping
Raleigh	NC0020389	4	Benson WWTP	Town of Benson	Johnston	06/21/2018	Not Compliant	06/21/2018	Other Violation	Violation detected during inspection	Records/Reports
Mooresville	NC0020737	4	Pilot Creek WWTP	City of Kings Mountain	Cleveland	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Pretreatment
Mooresville	NC0020737	4	Pilot Creek WWTP	City of Kings Mountain	Cleveland	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Pretreatment
Mooresville	NC0020737	4	Pilot Creek WWTP	City of Kings Mountain	Cleveland	07/19/2017	Not Compliant	07/19/2017		Violation detected during inspection	Pretreatment
Asheville	NC0020800	4	Andrews WWTP	Town of Andrews	Cherokee	04/10/2018	Not Compliant	04/10/2018		Violation detected during inspection	Pump Station - Influent
							•			5 .	·
Asheville	NC0020800	4	Andrews WWTP	Town of Andrews	Cherokee	04/10/2018	Not Compliant	04/10/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Bar Screens
Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Bar Screens
Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Disinfection-Liquid
Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Disinfection-Liquid
, is not me		·	manphy www.	Town or marpiny	CHEFORCE		rtot compilant		other violation	violation detected daring inspection	Bisimeotion Eigara
Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
-	·-		. ,	- r <i>i</i>		,,		,,		0 webecome	,
Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Pretreatment

Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Pretreatment
Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Sequencing Batch Reactors
Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Sequencing Batch Reactors
Asheville	NC0020940	4	Murphy WWTP	Town of Murphy	Cherokee	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Standby Power
Mooresville	NC0021156	4	Mount Holly WWTP	City of Mount Holly	Gaston	01/13/2018	Not Compliant	01/13/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Winston-Salem	NC0021491	4	Dutchman Creek WWTP	Town of Mocksville	Davie	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Aerobic Digester
Winston-Salem	NC0021491	4	Dutchman Creek WWTP	Town of Mocksville	Davie	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Aerobic Digester
Winston-Salem	NC0021491	4	Dutchman Creek WWTP	Town of Mocksville	Davie	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Disinfection-Gas
Winston-Salem	NC0021491	4	Dutchman Creek WWTP	Town of Mocksville	Davie	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Winston-Salem	NC0021491	4	Dutchman Creek WWTP	Town of Mocksville	Davie	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Winston-Salem	NC0021491	4	Dutchman Creek WWTP	Town of Mocksville	Davie	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Flow Measurement - Influent
Winston-Salem	NC0021491	4	Dutchman Creek WWTP	Town of Mocksville	Davie	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Flow Measurement - Influent
Winston-Salem Winston-Salem	NC0021491 NC0021491	4 4	Dutchman Creek WWTP Dutchman Creek WWTP	Town of Mocksville Town of Mocksville	Davie Davie	07/25/2017 07/25/2017	Not Compliant Not Compliant	07/25/2017 07/25/2017		Violation detected during inspection Violation detected during inspection	Record Keeping Record Keeping
Fayetteville	NC0021504	4	Biscoe WWTP	Town of Biscoe	Montgomery	03/20/2018	Not Compliant	03/20/2018	Other Violation	Permit conditions violation	Pretreatment
Winston-Salem	NC0021709	4	Jefferson WWTP	Town of Jefferson	Ashe	06/13/2018	Not Compliant	06/13/2018	Other Violation	Violation detected during inspection	Pretreatment
Winston-Salem	NC0021717	4	Cub Creek WWTP	Town of Wilkesboro	Wilkes	01/12/2018	Not Compliant	01/12/2018		Violation detected during inspection	Other
Winston-Salem	NC0021717	4	Cub Creek WWTP	Town of Wilkesboro	Wilkes	01/12/2018	Not Compliant	01/12/2018		Violation detected during inspection	Other
Winston-Salem Mooresville	NC0021873 NC0022934	4 4	Mayodan WWTP UCS Main Plant	Town of Mayodan UCS, Inc	Rockingham Gaston	06/11/2018 05/22/2018	Not Compliant Not Compliant	06/11/2018 05/22/2018		Violation detected during inspection Violation detected during inspection	Pretreatment Lagoons
Mooresville	NC0022934	4	UCS Main Plant	UCS, Inc	Gaston	05/22/2018	Not Compliant	05/22/2018	Other Violation	Violation detected during inspection	Operations & Maintenance

05/22/2018 Not Compliant 05/22/2018 Other Violation Violation detected during inspection

Permit

NC0022934

Mooresville

4 UCS Main Plant

UCS, Inc

Gaston

Mooresville	NC0023540	4	Belmont Textile Machinery WW	F Belmont Textile Machinery Company	Gaston	07/05/2017	Not Compliant	07/05/2017	Other Violation	Violation detected during inspection	Aeration Basins
Mooresville	NC0023540	4	Belmont Textile Machinery WW	F Belmont Textile Machinery Company	Gaston	07/05/2017	Not Compliant	07/05/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Mooresville	NC0024252	4	Northeast WWTP	City of Conover	Catawba	07/27/2017	Not Compliant	07/27/2017	Other Violation	Violation detected during inspection	Pretreatment
Winston-Salem	NC0024881	4	Reidsville WWTP	City of Reidsville	Rockingham	02/21/2018	Not Compliant	02/21/2018	Other Violation	Violation detected during inspection	Effluent Sampling
Winston-Salem Winston-Salem	NC0024881 NC0024881	4 4	Reidsville WWTP Reidsville WWTP	City of Reidsville City of Reidsville	Rockingham Rockingham	02/21/2018 02/21/2018	Not Compliant Not Compliant	02/21/2018 02/21/2018		Violation detected during inspection Violation detected during inspection	Pump Station - Influent Standby Power
Mooresville	NC0025496	5	Lincolnton WWTP	City of Lincolnton	Lincoln	04/19/2018	Not Compliant	04/19/2018	Other Violation	Violation detected during inspection	Drying Beds

Asheville	NC0025534	4	Hendersonville WWTP	City of Hendersonville	Henderson	02/08/2018	Not Compliant	02/08/2018	Other Violation	Violation detected during inspection	Flow Measurement - Influent
Asheville	NC0025836	4	Hot Springs WWTP	Town of Hot Springs	Madison	01/26/2018	Not Compliant	01/26/2018	Other Violation	Violation detected during inspection	Aeration Basins
Asheville	NC0025836	4	Hot Springs WWTP	Town of Hot Springs	Madison	01/26/2018	Not Compliant	01/26/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0025836	4	Hot Springs WWTP	Town of Hot Springs	Madison	01/26/2018	Not Compliant	01/26/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0025836	4	Hot Springs WWTP	Town of Hot Springs	Madison	01/26/2018	Not Compliant	01/26/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0025836	4	Hot Springs WWTP	Town of Hot Springs	Madison	01/26/2018	Not Compliant	01/26/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0025836	4	Hot Springs WWTP	Town of Hot Springs	Madison	01/26/2018	Not Compliant	01/26/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Winston-Salem	NC0028746	5	Briarwood Subdivision WWTP	Aqua North Carolina Inc	Stokes	10/27/2017	Not Compliant	10/27/2017	Other Violation	Violation detected during inspection	Permit
Winston-Salem	NC0028746	5	Briarwood Subdivision WWTP	Aqua North Carolina Inc	Stokes	10/27/2017	Not Compliant	10/27/2017	Other Violation	Violation detected during inspection	Secondary Clarifier
Winston-Salem	NC0030473	5	Mill Ridge Development WWTF	Mill Ridge Property Owners Association	Watauga	06/27/2018	Not Compliant	06/27/2018	Other Violation	Violation detected during inspection	Aeration Basins
Winston-Salem	NC0030473	5	Mill Ridge Development WWTF	P Mill Ridge Property Owners Association	Watauga	06/27/2018	Not Compliant	06/27/2018	Other Violation	Violation detected during inspection	Disinfection - UV
Washington	NC0032077	4	Contentnea Sewerage District WWTP	Contentnea Metropolitan Sewerage District	Pitt	05/09/2018	Not Compliant	05/09/2018	Other Violation	Violation detected during inspection	Pretreatment
Washington	NC0032077	4	Contentnea Sewerage District WWTP	Contentnea Metropolitan Sewerage District	Pitt	05/09/2018	Not Compliant	05/09/2018	Other Violation	Violation detected during inspection	Pretreatment
Winston-Salem	NC0032191	5	Hebron Colony & Grace Home WWTP	Hebron Colony Ministries In	Watauga	06/27/2018	Not Compliant	06/27/2018	Other Violation	Violation detected during inspection	Aeration Basins
Winston-Salem	NC0032191	5	Hebron Colony & Grace Home WWTP	Hebron Colony Ministries In	Watauga	06/27/2018	Not Compliant	06/27/2018	Other Violation	Violation detected during inspection	Disinfection - UV
Winston-Salem	NC0032191	5	Hebron Colony & Grace Home WWTP	Hebron Colony Ministries In	Watauga	06/27/2018	Not Compliant	06/27/2018	Other Violation	Violation detected during inspection	Permit

Winston-Salem	NC0032191	5	Hebron Colony & Grace Home WWTP	Hebron Colony Ministries In	Watauga	06/27/2018	Not Compliant	06/27/2018	Other Violation	Violation detected during inspection	Record Keeping
Mooresville	NC0032867	4	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Aeration Basins
Mooresville	NC0032867	4	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Flow Measurement - Effluent
Mooresville	NC0032867	1	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	09/06/2017	Not Compliant	09/06/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Mooresville	NC0032867	4	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	09/06/2017	Not Compliant	09/06/2017		Violation detected during inspection	Record Keeping
	NC0032867	4	Kings Mountain Travel Plaza	Maliks International Inc		12/11/2017	·	12/11/2017		Violation detected during inspection	Operations & Maintenance
Mooresville	NC0032807	4	Kings Mountain Travel Plaza	Maliks international inc	Cleveland	12/11/2017	Not Compliant	12/11/2017	Other violation	violation detected during inspection	Operations & Maintenance
Mooresville	NC0032867	4	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	12/11/2017	Not Compliant	12/11/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Mooresville	NC0032867	4	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	12/11/2017	Not Compliant	12/11/2017	Other Violation	Violation detected during inspection	Permit
Magraguilla	NC0032867	4	Kings Mountain Traval Blaza	Malike International Inc	Claveland	12/11/2017	Not Compliant	12/11/2017	Other Vielation	Violation detected during inspection	Dormit
Mooresville	NC0052807	4	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	12/11/2017	Not Compliant	12/11/2017	Other violation	Violation detected during inspection	Permit
Mooresville	NC0032867	4	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	02/01/2018	Not Compliant	02/01/2018	Other Violation	Violation detected during inspection	Flow Measurement - Effluent
Mooresville	NC0032867	4	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	02/01/2018	Not Compliant	02/01/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Mooresville	NC0032867	4	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	02/01/2018	Not Compliant	02/01/2018	Other Violation	Violation detected during inspection	Record Keeping
Mooresville	NC0032867	4	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	02/01/2018	Not Compliant	02/01/2018	Other Violation	Violation detected during inspection	Record Keeping
Mooresville Mooresville	NC0032867 NC0032867	4	Kings Mountain Travel Plaza Kings Mountain Travel Plaza	Maliks International Inc Maliks International Inc	Cleveland	02/01/2018	Not Compliant Not Compliant	02/01/2018		Violation detected during inspection Violation detected during inspection	Record Keeping Septic Tank
		4	ū				·			ŭ ,	
		4 4 5	ū				·		Other Violation	ŭ ,	
Mooresville	NC0032867	4 4 5 5	Kings Mountain Travel Plaza	Maliks International Inc	Cleveland	02/01/2018	Not Compliant	02/01/2018	Other Violation Other Violation	Violation detected during inspection	Septic Tank
Mooresville Asheville	NC0032867 NC0034924		Kings Mountain Travel Plaza Flesher's Fairview Rest Home	Maliks International Inc Flesher's Fairview Rest Hom	Cleveland Buncombe	02/01/2018	Not Compliant Not Compliant	02/01/2018	Other Violation Other Violation Other Violation	Violation detected during inspection Violation detected during inspection	Septic Tank De-chlorination
Mooresville Asheville Asheville	NC0032867 NC0034924 NC0034924	5	Kings Mountain Travel Plaza Flesher's Fairview Rest Home Flesher's Fairview Rest Home	Maliks International Inc Flesher's Fairview Rest Hom Flesher's Fairview Rest Hom	Cleveland Buncombe Buncombe	02/01/2018 10/04/2017 10/04/2017	Not Compliant Not Compliant Not Compliant	02/01/2018 10/04/2017 10/04/2017	Other Violation Other Violation Other Violation Other Violation	Violation detected during inspection Violation detected during inspection Violation detected during inspection	Septic Tank De-chlorination Disinfection-Tablet
Mooresville Asheville Asheville Asheville	NC0032867 NC0034924 NC0034924 NC0034924	5	Kings Mountain Travel Plaza Flesher's Fairview Rest Home Flesher's Fairview Rest Home Flesher's Fairview Rest Home	Maliks International Inc Flesher's Fairview Rest Hom Flesher's Fairview Rest Hom Flesher's Fairview Rest Hom	Cleveland Buncombe Buncombe Buncombe	02/01/2018 10/04/2017 10/04/2017 10/04/2017	Not Compliant Not Compliant Not Compliant Not Compliant	02/01/2018 10/04/2017 10/04/2017 10/04/2017	Other Violation Other Violation Other Violation Other Violation	Violation detected during inspection Violation detected during inspection Violation detected during inspection Violation detected during inspection	Septic Tank De-chlorination Disinfection-Tablet Effluent Pipe
Mooresville Asheville Asheville Asheville	NC0032867 NC0034924 NC0034924 NC0034924	5	Kings Mountain Travel Plaza Flesher's Fairview Rest Home Flesher's Fairview Rest Home Flesher's Fairview Rest Home	Maliks International Inc Flesher's Fairview Rest Hom Flesher's Fairview Rest Hom Flesher's Fairview Rest Hom	Cleveland Buncombe Buncombe Buncombe	02/01/2018 10/04/2017 10/04/2017 10/04/2017	Not Compliant Not Compliant Not Compliant Not Compliant	02/01/2018 10/04/2017 10/04/2017 10/04/2017	Other Violation Other Violation Other Violation Other Violation Other Violation	Violation detected during inspection Violation detected during inspection Violation detected during inspection Violation detected during inspection	Septic Tank De-chlorination Disinfection-Tablet Effluent Pipe
Mooresville Asheville Asheville Asheville Asheville	NC0032867 NC0034924 NC0034924 NC0034924 NC0034924	5 5 5	Kings Mountain Travel Plaza Flesher's Fairview Rest Home Flesher's Fairview Rest Home Flesher's Fairview Rest Home Flesher's Fairview Rest Home	Maliks International Inc Flesher's Fairview Rest Hom Flesher's Fairview Rest Hom Flesher's Fairview Rest Hom Flesher's Fairview Rest Hom	Cleveland Buncombe Buncombe Buncombe Buncombe	02/01/2018 10/04/2017 10/04/2017 10/04/2017 10/04/2017	Not Compliant Not Compliant Not Compliant Not Compliant Not Compliant	02/01/2018 10/04/2017 10/04/2017 10/04/2017 10/04/2017	Other Violation Other Violation Other Violation Other Violation Other Violation Other Violation	Violation detected during inspection	Septic Tank De-chlorination Disinfection-Tablet Effluent Pipe Effluent Sampling
Mooresville Asheville Asheville Asheville Asheville	NC0032867 NC0034924 NC0034924 NC0034924 NC0034924	5 5 5	Kings Mountain Travel Plaza Flesher's Fairview Rest Home Flesher's Fairview Rest Home Flesher's Fairview Rest Home Flesher's Fairview Rest Home	Maliks International Inc Flesher's Fairview Rest Hom Cleveland Buncombe Buncombe Buncombe Buncombe	02/01/2018 10/04/2017 10/04/2017 10/04/2017 10/04/2017	Not Compliant Not Compliant Not Compliant Not Compliant Not Compliant	02/01/2018 10/04/2017 10/04/2017 10/04/2017 10/04/2017	Other Violation	Violation detected during inspection	Septic Tank De-chlorination Disinfection-Tablet Effluent Pipe Effluent Sampling Operations & Maintenance	
Mooresville Asheville Asheville Asheville Asheville Asheville	NC0032867 NC0034924 NC0034924 NC0034924 NC0034924 NC0034924	5 5 5 5	Kings Mountain Travel Plaza Flesher's Fairview Rest Home Maliks International Inc Flesher's Fairview Rest Hom Cleveland Buncombe Buncombe Buncombe Buncombe Buncombe	02/01/2018 10/04/2017 10/04/2017 10/04/2017 10/04/2017 10/04/2017	Not Compliant Not Compliant Not Compliant Not Compliant Not Compliant Not Compliant	02/01/2018 10/04/2017 10/04/2017 10/04/2017 10/04/2017 10/04/2017	Other Violation	Violation detected during inspection Septic Tank De-chlorination Disinfection-Tablet Effluent Pipe Effluent Sampling Operations & Maintenance Secondary Clarifier			

Washington	NC0036315	5	Roper WWTP	Town of Roper	Washington	02/14/2018	Not Compliant	02/14/2018	Other Violation	Violation detected during inspection	Disinfection - UV
Washington	NC0036919	4	Pantego Municipal Center WWTP	Town of Pantego	Beaufort	04/17/2018	Not Compliant	04/17/2018	Other Violation	Violation detected during inspection	Disinfection - UV
Washington	NC0036919	4	Pantego Municipal Center WWTP	Town of Pantego	Beaufort	04/17/2018	Not Compliant	04/17/2018	Other Violation	Violation detected during inspection	Flow Measurement - Effluent
Washington	NC0036919	4	Pantego Municipal Center WWTP	Town of Pantego	Beaufort	04/17/2018	Not Compliant	04/17/2018	Other Violation	Violation detected during inspection	Pump Station - Influent
Washington	NC0036919	4	Pantego Municipal Center WWTP	Town of Pantego	Beaufort	04/17/2018	Not Compliant	04/17/2018	Other Violation	Violation detected during inspection	Record Keeping
Washington	NC0036919	4	Pantego Municipal Center WWTP	Town of Pantego	Beaufort	04/17/2018	Not Compliant	04/17/2018	Other Violation	Violation detected during inspection	Record Keeping
Mooresville	NC0039594	4	Maiden WWTP	Town of Maiden	Catawba	10/31/2017	Not Compliant	10/31/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Mooresville	NC0039594	4	Maiden WWTP	Town of Maiden	Catawba	10/31/2017	Not Compliant	10/31/2017	Other Violation	Violation detected during inspection	Flow Measurement - Influent
Mooresville	NC0039594	4	Maiden WWTP	Town of Maiden	Catawba	10/31/2017	Not Compliant	10/31/2017	Other Violation	Violation detected during inspection	Grit Removal
Mooresville Mooresville	NC0039594 NC0039594	4	Maiden WWTP Maiden WWTP	Town of Maiden Town of Maiden	Catawba Catawba	10/31/2017 10/31/2017	Not Compliant Not Compliant	10/31/2017 10/31/2017		Violation detected during inspection Violation detected during inspection	Influent Sampling Laboratory
Asheville	NC0042358	4	Adams Apple Condominiums	Adams Apple Homeowners	Avery	08/17/2017	Not Compliant	08/17/2017	Other Violation	Permit conditions violation	Effluent Sampling
Raleigh	NC0042510	4	WWTP Lake Royale WWTP	Association Inc Total Environmental Solutions Inc	Franklin	11/13/2017	Not Compliant	11/13/2017	Other Violation	Violation detected during inspection	Bar Screens
Raleigh	NC0042510	4	Lake Royale WWTP	Total Environmental Solutions Inc	Franklin	11/13/2017	Not Compliant	11/13/2017	Other Violation	Violation detected during inspection	Filtration (High Rate Tertiary)
Raleigh	NC0042510	4	Lake Royale WWTP	Total Environmental Solutions Inc	Franklin	11/13/2017	Not Compliant	11/13/2017	Other Violation	Violation detected during inspection	Permit
Raleigh	NC0042510	4	Lake Royale WWTP	Total Environmental Solutions Inc	Franklin	11/13/2017	Not Compliant	11/13/2017	Other Violation	Violation detected during inspection	Standby Power
Mooresville	NC0044253	4	Camp Dogwood WWTP	North Carolina Lions Foundation Inc	Catawba	04/03/2018	Not Compliant	04/03/2018	Other Violation	Violation detected during inspection	De-chlorination
Mooresville	NC0044253	4	Camp Dogwood WWTP	North Carolina Lions Foundation Inc	Catawba	04/03/2018	Not Compliant	04/03/2018	Other Violation	Violation detected during inspection	Disinfection-Tablet
Mooresville	NC0044253	4	Camp Dogwood WWTP	North Carolina Lions Foundation Inc	Catawba	04/03/2018	Not Compliant	04/03/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Mooresville	NC0044253	4	Camp Dogwood WWTP	North Carolina Lions	Catawba	04/03/2018	Not Compliant	04/03/2018	Other Violation	Violation detected during inspection	Record Keeping
Mooresville	NC0044440	5	Cherryville WWTP	Foundation Inc City of Cherryville	Gaston	01/30/2018	Not Compliant	01/30/2018	Other Violation	Violation detected during inspection	Record Keeping
Asheville	NC0049620	4	Hot Springs Housing Authority WWTP	Town of Hot Springs	Madison	01/26/2018	Not Compliant	01/26/2018	Other Violation	Violation detected during inspection	Sand Filters (Low rate)

Asheville	NC0049620	4	Hot Springs Housing Authority	Town of Hot Springs	Madison	01/26/2018	Not Compliant	01/26/2018	Other Violation	Violation detected during inspection	Sand Filters (Low rate)
Asheville	NC0049620	4	WWTP Hot Springs Housing Authority WWTP	Town of Hot Springs	Madison	01/26/2018	Not Compliant	01/26/2018	Other Violation	Violation detected during inspection	Sand Filters (Low rate)
Asheville	NC0049620	4	Hot Springs Housing Authority	Town of Hot Springs	Madison	01/26/2018	Not Compliant	01/26/2018	Other Violation	Violation detected during inspection	Septic Tank
Mooresville	NC0049867	4	WWTP Cleveland WWTP	Town of Cleveland	Rowan	05/29/2018	Not Compliant	05/29/2018	Other Violation	Violation detected during inspection	Aerobic Digester
Mooresville	NC0049867	4	Cleveland WWTP	Town of Cleveland	Rowan	05/29/2018	Not Compliant	05/29/2018	Other Violation	Violation detected during inspection	Drying Beds
Mooresville	NC0049867	4	Cleveland WWTP	Town of Cleveland	Rowan	05/29/2018	Not Compliant	05/29/2018	Other Violation	Violation detected during inspection	Oxidation Ditches
Mooresville Mooresville	NC0049867 NC0049867	4	Cleveland WWTP Cleveland WWTP	Town of Cleveland Town of Cleveland	Rowan Rowan	05/29/2018 06/12/2018	Not Compliant Not Compliant	05/29/2018 06/12/2018		Violation detected during inspection Violation detected during inspection	Pumps-RAS-WAS Pretreatment
Winston-Salem	NC0050610	5	The Ponds WWTP	Water Quality Utilities Inc	Watauga	06/27/2018	Not Compliant	06/27/2018	Other Violation	Violation detected during inspection	Disinfection - UV
Winston-Salem Winston-Salem	NC0050610 NC0050610	5 5	The Ponds WWTP The Ponds WWTP	Water Quality Utilities Inc Water Quality Utilities Inc	Watauga Watauga	06/27/2018 06/27/2018	Not Compliant Not Compliant	06/27/2018 06/27/2018		Violation detected during inspection Violation detected during inspection	Effluent Sampling Record Keeping
Winston-Salem	NC0050610	5	The Ponds WWTP	Water Quality Utilities Inc	Watauga	06/27/2018	Not Compliant	06/27/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Winston-Salem	NC0051713	4	Lakeview Mobile Home Park WWTP	Lakeview MHP LLC	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Aeration Basins
Winston-Salem	NC0051713	4	Lakeview Mobile Home Park WWTP	Lakeview MHP LLC	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Flow Measurement - Effluent
Winston-Salem	NC0051713	4	Lakeview Mobile Home Park WWTP	Lakeview MHP LLC	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Permit
Winston-Salem	NC0051713	4	Lakeview Mobile Home Park WWTP	Lakeview MHP LLC	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Record Keeping
Winston-Salem	NC0059536	4	Hilltop Living Center WWTP	Tisha Tuttle	Davidson	03/14/2018	Not Compliant	03/14/2018	Other Violation	Violation detected during inspection	Laboratory
Winston-Salem Winston-Salem	NC0059536 NC0059536	4 4	Hilltop Living Center WWTP Hilltop Living Center WWTP	Tisha Tuttle Tisha Tuttle	Davidson Davidson	03/14/2018 03/14/2018	Not Compliant Not Compliant	03/14/2018 03/14/2018		Violation detected during inspection Violation detected during inspection	Record Keeping Record Keeping
Winston-Salem	NC0059536	4	Hilltop Living Center WWTP	Tisha Tuttle	Davidson	03/14/2018	Not Compliant	03/14/2018	Other Violation	Violation detected during inspection	Upstream / Downstream Sampling
Raleigh	NC0060526	4	Pope Industrial Park	Pope Industrial Park II Ltd Partnership	Wake	02/27/2018	Not Compliant	02/27/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Raleigh	NC0060526	4	Pope Industrial Park	Pope Industrial Park II Ltd Partnership	Wake	02/27/2018	Not Compliant	02/27/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Raleigh	NC0060526	4	Pope Industrial Park	Pope Industrial Park II Ltd Partnership	Wake	02/27/2018	Not Compliant	02/27/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Raleigh	NC0060526	4	Pope Industrial Park	Pope Industrial Park II Ltd Partnership	Wake	02/27/2018	Not Compliant	02/27/2018	Other Violation	Violation detected during inspection	Permit

Winston-Salem	NC0061204	4	Scarlett Acres MHP WWTP	Thomas Alphin	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Aeration Basins
Winston-Salem	NC0061204	4	Scarlett Acres MHP WWTP	Thomas Alphin	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Bar Screens
Winston-Salem Winston-Salem Winston-Salem Winston-Salem Winston-Salem	NC0061204 NC0061204 NC0061204 NC0061204 NC0061204	4 4 4 4	Scarlett Acres MHP WWTP	Thomas Alphin Thomas Alphin Thomas Alphin Thomas Alphin Thomas Alphin	Forsyth Forsyth Forsyth Forsyth	06/05/2018 06/05/2018 06/05/2018 06/05/2018 06/05/2018	Not Compliant Not Compliant Not Compliant Not Compliant Not Compliant	06/05/2018 06/05/2018 06/05/2018 06/05/2018 06/05/2018	Other Violation Other Violation Other Violation	Violation detected during inspection Violation detected during inspection Violation detected during inspection Violation detected during inspection Violation detected during inspection	Effluent Pipe Operations & Maintenance Permit Pump Station - Effluent Pump Station - Influent
Winston-Salem Winston-Salem Mooresville Mooresville	NC0061204 NC0061204 NC0062278 NC0062278	4 4 5	Scarlett Acres MHP WWTP Scarlett Acres MHP WWTP Berkley Oaks WWTP Berkley Oaks WWTP	Thomas Alphin Thomas Alphin Berkley Oaks LLC Berkley Oaks LLC	Forsyth Forsyth Gaston Gaston	06/05/2018 06/05/2018 12/06/2017 12/06/2017	Not Compliant Not Compliant Not Compliant Not Compliant	06/05/2018 06/05/2018 12/06/2017 12/06/2017	Other Violation Other Violation	Violation detected during inspection Violation detected during inspection Violation detected during inspection Violation detected during inspection	Record Keeping Secondary Clarifier Bar Screens Operations & Maintenance
Mooresville	NC0062278	5	Berkley Oaks WWTP	Berkley Oaks LLC	Gaston	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Aeration Basins
Mooresville	NC0062278	5	Berkley Oaks WWTP	Berkley Oaks LLC	Gaston	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Bar Screens
Mooresville Mooresville	NC0062278 NC0062278	5 5	Berkley Oaks WWTP Berkley Oaks WWTP	Berkley Oaks LLC Berkley Oaks LLC	Gaston Gaston	02/22/2018 02/22/2018	Not Compliant Not Compliant	02/22/2018 02/22/2018		Violation detected during inspection Violation detected during inspection	Disinfection-Tablet Effluent Sampling
Mooresville	NC0062278	5	Berkley Oaks WWTP	Berkley Oaks LLC	Gaston	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Mooresville	NC0062278	5	Berkley Oaks WWTP	Berkley Oaks LLC	Gaston	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Record Keeping
Mooresville	NC0062278	5	Berkley Oaks WWTP	Berkley Oaks LLC	Gaston	02/22/2018	Not Compliant	02/22/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Asheville	NC0062413	4	Linville Ridge Country Club	Linville Ridge Country Club	Avery	08/17/2017	Not Compliant	08/17/2017	Other Violation	Improper operation and maintenance	Permit
Mooresville	NC0063762	4	WWTP Carolina Village Mobile Home	Carolina Village Mhc LLC	Cabarrus	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Aerobic Digester
Mooresville	NC0063762	4	Park Carolina Village Mobile Home	Carolina Village Mhc LLC	Cabarrus	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Bar Screens
Mooresville	NC0063762	4	Park Carolina Village Mobile Home	Carolina Village Mhc LLC	Cabarrus	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Bar Screens
Mooresville	NC0063762	4	Park Carolina Village Mobile Home Park	Carolina Village Mhc LLC	Cabarrus	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Mooresville	NC0063762	4	Carolina Village Mobile Home Park	Carolina Village Mhc LLC	Cabarrus	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Effluent Sampling

Mooresville	NC0063762	4	Carolina Village Mobile Home Park	Carolina Village Mhc LLC	Cabarrus	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Mooresville	NC0063762	4	Carolina Village Mobile Home Park	Carolina Village Mhc LLC	Cabarrus	07/25/2017	Not Compliant	07/25/2017	Other Violation	Violation detected during inspection	Secondary Clarifier
Raleigh	NC0064246	4	Pace Mobile Home Park	Joel Pace	Johnston	07/07/2017	Not Compliant	07/07/2017	Other Violation	Violation detected during inspection	Effluent/Receiving Waters
Raleigh	NC0064246	4	Pace Mobile Home Park	Joel Pace	Johnston	07/07/2017	Not Compliant	07/07/2017	Other Violation	Violation detected during inspection	Effluent/Receiving Waters
Mooresville	NC0064599	4	Lake Norman Motel WWTP	Halina Genaro	Catawba	04/03/2018	Not Compliant	04/03/2018	Other Violation	Violation detected during inspection	Disinfection-Tablet
Raleigh	NC0064891	4	Kenly Regional WWTP	Town of Kenly	Johnston	07/31/2017	Not Compliant	07/31/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Raleigh	NC0064891	4	Kenly Regional WWTP	Town of Kenly	Johnston	07/31/2017	Not Compliant	07/31/2017	Other Violation	Violation detected during inspection	Nutrient Removal
Raleigh	NC0064891	4	Kenly Regional WWTP	Town of Kenly	Johnston	07/31/2017	Not Compliant	07/31/2017		Improper operation and maintenance	Operations & Maintenance
Raleigh	NC0064891	4	Kenly Regional WWTP	Town of Kenly	Johnston	07/31/2017	Not Compliant	07/31/2017		Permit conditions violation	Permit
Raleigh	NC0064891	4	Kenly Regional WWTP	Town of Kenly	Johnston	07/31/2017	Not Compliant	07/31/2017		ORC Violation	Permit
Raleigh	NC0064891	4	Kenly Regional WWTP	Town of Kenly	Johnston	07/31/2017	Not Compliant	07/31/2017	Other Violation	Violation detected during inspection	Permit
Mooresville	NC0065242	4	Grover WWTP	Town of Grover	Cleveland	12/13/2017	Not Compliant	12/13/2017	Other Violation	Violation detected during inspection	Bar Screens
Mooresville	NC0065242	4	Grover WWTP	Town of Grover	Cleveland	12/13/2017	Not Compliant	12/13/2017	Other Violation	Violation detected during inspection	Effluent Pipe
Mooresville	NC0065242	4	Grover WWTP	Town of Grover	Cleveland	12/13/2017	Not Compliant	12/13/2017	Other Violation	Violation detected during inspection	Flow Measurement - Effluent
Mooresville	NC0065242	4	Grover WWTP	Town of Grover	Cleveland	12/13/2017	Not Compliant	12/13/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Mooresville	NC0065242	4	Grover WWTP	Town of Grover	Cleveland	12/13/2017	Not Compliant	12/13/2017	Other Violation	Violation detected during inspection	Record Keeping
Mooresville	NC0065242	4	Grover WWTP	Town of Grover	Cleveland	12/13/2017	Not Compliant	12/13/2017	Other Violation	Violation detected during inspection	Secondary Clarifier
							·			-	
Raleigh	NC0065706	4	Cottonwood / Baywood WWTF	·	Wake	12/04/2017	Not Compliant	12/04/2017		Violation detected during inspection	Bar Screens
Raleigh	NC0065706	4	Cottonwood / Baywood WWTF	Crosby Utilities Inc	Wake	12/04/2017	Not Compliant	12/04/2017	Other Violation	Permit conditions violation	Other
Raleigh	NC0065706	4	Cottonwood / Baywood WWTF	P Crosby Utilities Inc	Wake	12/04/2017	Not Compliant	12/04/2017	Other Violation	Violation detected during inspection	Other
Raleigh	NC0065706	4	Cottonwood / Baywood WWTF	Crosby Utilities Inc	Wake	12/04/2017	Not Compliant	12/04/2017	Other Violation	Failure to meet a schedule date	
Asheville	NC0066362	4	Benson Apartments	Nathan Benson	Henderson	05/09/2018	Not Compliant	05/09/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0066362	4	Benson Apartments	Nathan Benson	Henderson	05/09/2018	Not Compliant	05/09/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0066362	4	Benson Apartments	Nathan Benson	Henderson	05/09/2018	Not Compliant	05/09/2018	Other Violation	Violation detected during inspection	Permit

Asheville Winston-Salem	NC0066362 NC0066966	4 3	Benson Apartments Quarterstone Farm WWTP	Nathan Benson Quarterstone Farm Homeowners Association	Henderson Guilford	05/09/2018 03/07/2018	Not Compliant Not Compliant	05/09/2018 03/07/2018		Violation detected during inspection Violation detected during inspection	Permit Pump Station - Influent
Winston-Salem	NC0066966	3	Quarterstone Farm WWTP	Quarterstone Farm Homeowners Association	Guilford	03/07/2018	Not Compliant	03/07/2018	Other Violation	Failure to achieve compliance with final effluent limitations at final complianc	Self-Monitoring Program
Asheville	NC0067288	4	Hunter's Glen WWTP	A&D Water Service Inc	Henderson	05/15/2018	Not Compliant	05/15/2018	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville Asheville	NC0067288 NC0067342	4 2	Hunter's Glen WWTP North View Mobile Home Park	A&D Water Service Inc Eaven Brice Partnership	Henderson Buncombe	05/15/2018 12/13/2017	Not Compliant Not Compliant	05/15/2018 12/13/2017		Violation detected during inspection Violation detected during inspection	Flow Measurement - Effluent Permit
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Aeration Basins
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Aeration Basins
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Compliance Schedules
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Disinfection-Tablet
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Flow Measurement - Effluent
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Record Keeping
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/01/2018	Not Compliant	06/01/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Disinfection-Tablet
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Flow Measurement - Effluent
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Asheville	NC0067342	3	North View Mobile Home Park	Eaven Brice Partnership	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Secondary Clarifier

Asheville	NC0068152	4	Eden Glen Mobile Village WWTP	Dry Ridge Properties LLC	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Aeration Basins
Asheville	NC0068152	4	Eden Glen Mobile Village WWTP	Dry Ridge Properties LLC	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Disinfection-Tablet
Asheville	NC0068152	4	Eden Glen Mobile Village WWTP	Dry Ridge Properties LLC	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0068152	4	Eden Glen Mobile Village WWTP	Dry Ridge Properties LLC	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0068152	4	Eden Glen Mobile Village WWTP	Dry Ridge Properties LLC	Buncombe	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Asheville	NC0068799	4	Greystone Subdivision	Greystone Enterprises Inc	Henderson	09/07/2017	Not Compliant	09/07/2017	Other Violation	Violation detected during inspection	Disinfection-Tablet
Asheville	NC0068799	4	Greystone Subdivision	Greystone Enterprises Inc	Henderson	09/07/2017	Not Compliant	09/07/2017	Other Violation	Violation detected during inspection	Disinfection-Tablet
Asheville	NC0068799	4	Greystone Subdivision	Greystone Enterprises Inc	Henderson	09/07/2017	Not Compliant	09/07/2017	Other Violation	Failure to achieve compliance with final effluent limitations at final complianc	Effluent Sampling
Asheville	NC0068799	4	Greystone Subdivision	Greystone Enterprises Inc	Henderson	09/07/2017	Not Compliant	09/07/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0068799	4	Greystone Subdivision	Greystone Enterprises Inc	Henderson	09/07/2017	Not Compliant	09/07/2017	Other Violation	Failure to achieve compliance with final effluent limitations at final complianc	Effluent Sampling
Asheville	NC0068799	4	Greystone Subdivision	Greystone Enterprises Inc	Henderson	09/07/2017	Not Compliant	09/07/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0068799	4	Greystone Subdivision	Greystone Enterprises Inc	Henderson	09/07/2017	Not Compliant	09/07/2017	Other Violation	Violation detected during inspection	Secondary Clarifier
Asheville	NC0068799	4	Greystone Subdivision	Greystone Enterprises Inc	Henderson	09/07/2017	Not Compliant	09/07/2017	Other Violation	Violation detected during inspection	Secondary Clarifier
Mooresville	NC0068888	5	Dallas WWTP	Town of Dallas	Gaston	10/25/2017	Not Compliant	10/25/2017	Other Violation	Violation detected during inspection	Bar Screens
Mooresville Mooresville	NC0068888 NC0068888	5 5	Dallas WWTP Dallas WWTP	Town of Dallas Town of Dallas	Gaston Gaston	10/25/2017 10/25/2017	Not Compliant Not Compliant	10/25/2017 10/25/2017		Violation detected during inspection Violation detected during inspection	Drying Beds Flow Measurement - Effluent
Mooresville	NC0068888	5	Dallas WWTP	Town of Dallas	Gaston	10/25/2017	Not Compliant	10/25/2017	Other Violation	Violation detected during inspection	Record Keeping
Asheville	NC0071897	4	Henderson's Assisted Living WWTP	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Permit conditions violation	Effluent Sampling
Asheville	NC0071897	4	Henderson's Assisted Living WWTP	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Permit conditions violation	Effluent Sampling
Asheville	NC0071897	4	Henderson's Assisted Living WWTP	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Improper operation and maintenance	Operations & Maintenance
Asheville	NC0071897	4	Henderson's Assisted Living WWTP	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Improper operation and maintenance	Operations & Maintenance
Asheville	NC0071897	4	Henderson's Assisted Living WWTP	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Improper operation and maintenance	Operations & Maintenance
Asheville	NC0071897	4	Henderson's Assisted Living WWTP	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Improper operation and maintenance	Operations & Maintenance
Asheville	NC0071897	4	Henderson's Assisted Living WWTP	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Violation detected during inspection	Bar Screens
Asheville	NC0071897	4	Henderson's Assisted Living WWTP	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Violation detected during inspection	Bar Screens
Asheville	NC0071897	4	Henderson's Assisted Living WWTP	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Failure to achieve compliance with final effluent limitations at final complianc	Permit
			VVVVIP								
Asheville	NC0071897	4	Henderson's Assisted Living WWTP	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	effluent limitations at final complianc	Permit
Asheville Asheville Asheville		4 4	Henderson's Assisted Living	Mizpah Healthcare Inc A&D Water Service Inc A&D Water Service Inc	Henderson Henderson Henderson	10/06/2017 05/15/2018 05/15/2018	Not Compliant Not Compliant Not Compliant	10/06/2017 05/15/2018 05/15/2018	Other Violation	effluent limitations at final complianc	Permit Effluent Pipe Effluent Sampling

Asheville Asheville	NC0073741 NC0074110	4 4	Mountain Valley WWTP Mountain View Assisted Living	A&D Water Service Inc Mizpah Healthcare Inc	Henderson Henderson	05/15/2018 07/19/2017	Not Compliant Not Compliant	05/15/2018 07/19/2017		Violation detected during inspection Violation detected during inspection	Operations & Maintenance Effluent Pipe
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Effluent Pipe
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	07/19/2017	Not Compliant	07/19/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Violation detected during inspection	Effluent Pipe
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Violation detected during inspection	Effluent Pipe
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Violation detected during inspection	Permit
Asheville	NC0074110	4	Mountain View Assisted Living	Mizpah Healthcare Inc	Henderson	10/06/2017	Not Compliant	10/06/2017	Other Violation	Violation detected during inspection	Permit
Fayetteville	NC0074390	4	Anson County WTP	Anson County	Anson	05/10/2018	Not Compliant	05/10/2018	Other Violation	Violation detected during inspection	Facility Site Review
Fayetteville	NC0074390	4	Anson County WTP	Anson County	Anson	05/10/2018 06/05/2018	Not Compliant	05/10/2018 06/05/2018		Violation detected during inspection Violation detected during inspection	Permit
Winston-Salem	NC0075027	5	Cainsway Mobile Home Park	Cainsway Homeowners Association	Forsyth	00/03/2018	Not Compliant	00/03/2018	Other violation	violation detected during inspection	Aeration Basins
Winston-Salem	NC0075027	5	Cainsway Mobile Home Park	Cainsway Homeowners Association	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Effluent Sampling
Winston-Salem	NC0075027	5	Cainsway Mobile Home Park	Cainsway Homeowners	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Permit
Winston-Salem	NC0075027	5	Cainsway Mobile Home Park	Association Cainsway Homeowners	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Pump Station - Influent
Winston-Salem	NC0075027	5	Cainsway Mobile Home Park	Association Cainsway Homeowners	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Record Keeping
Winston-Salem	NC0075027	5	Cainsway Mobile Home Park	Association Cainsway Homeowners	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Secondary Clarifier
Winston-Salem	NC0077135	5	Hidden Valley WWTP	Association Curl Modular Homes	Rockingham	07/17/2017	Not Compliant	07/17/2017	Other Violation	Violation detected during inspection	Bar Screens
Winston-Salem	NC0077135	5	Hidden Valley WWTP	Curl Modular Homes	Rockingham	07/17/2017	Not Compliant	07/17/2017	Other Violation	Violation detected during inspection	Disinfection - UV
Winston-Salem	NC0077135	5	Hidden Valley WWTP	Curl Modular Homes	Rockingham	07/17/2017	Not Compliant	07/17/2017	Other Violation	Violation detected during inspection	Laboratory
Winston-Salem	NC0077135	5	Hidden Valley WWTP	Curl Modular Homes	Rockingham	07/17/2017	Not Compliant	07/17/2017	Other Violation	Violation detected during inspection	Record Keeping

Winston-Salem	NC0077135	5	Hidden Valley WWTP	Curl Modular Homes	Rockingham	07/17/2017	Not Compliant	07/17/2017	Other Violation	Violation detected during inspection	Secondary Clarifier
Mooresville	NC0077615	4	Origin Food Group, LLC	Origin Food Group LLC	Iredell	02/01/2018	Not Compliant	02/01/2018	Other Violation	Violation detected during inspection	Aeration Basins
Mooresville	NC0077615	4	Origin Food Group, LLC	Origin Food Group LLC	Iredell	02/01/2018	Not Compliant	02/01/2018	Other Violation	Violation detected during inspection	Aeration Basins
Mooresville Mooresville Mooresville	NC0077615 NC0077615 NC0077615	4 4 4	Origin Food Group, LLC Origin Food Group, LLC Origin Food Group, LLC	Origin Food Group LLC Origin Food Group LLC Origin Food Group LLC	Iredell Iredell Iredell	02/01/2018 02/01/2018 02/01/2018	Not Compliant Not Compliant Not Compliant	02/01/2018 02/01/2018 02/01/2018	Other Violation	Violation detected during inspection Violation detected during inspection Violation detected during inspection	De-chlorination Effluent Pipe Pump Station - Influent
Mooresville Asheville	NC0077615 NC0080098	4	Origin Food Group, LLC Linville Falls Mountain Club and Preserve	Association Inc	Iredell McDowell	02/01/2018 07/07/2017	Not Compliant Not Compliant	02/01/2018 07/07/2017	Other Violation	Violation detected during inspection Permit conditions violation	Secondary Clarifier Effluent Pipe
Asheville Asheville	NC0080098 NC0080098	4	Linville Falls Mountain Club and Preserve Linville Falls Mountain Club and Preserve	Association Inc	McDowell McDowell	07/07/2017 07/07/2017	Not Compliant Not Compliant	07/07/2017		Permit conditions violation Permit conditions violation	Effluent Pipe Effluent Sampling
Asheville	NC0080098	4	Linville Falls Mountain Club and Preserve	Linville Falls Club Property Association Inc	McDowell	07/07/2017	Not Compliant	07/07/2017	Other Violation	Permit conditions violation	Effluent Sampling
Winston-Salem Winston-Salem	NC0082384 NC0082384	5 5	Danbury WWTP Danbury WWTP	Stokes County Stokes County	Stokes Stokes	12/20/2017 12/20/2017	Not Compliant Not Compliant	12/20/2017 12/20/2017		Violation detected during inspection Violation detected during inspection	Laboratory Laboratory
Winston-Salem	NC0082384	5	Danbury WWTP	Stokes County	Stokes	12/20/2017	Not Compliant	12/20/2017	Other Violation	Violation detected during inspection	Laboratory
Mooresville	NC0083887	4	Charlotte Douglas International Airport	City of Charlotte	Mecklenburg	02/12/2018	Not Compliant	02/12/2018	Other Violation	Violation detected during inspection	Facility Site Review
Mooresville	NC0083887	4	Charlotte Douglas International Airport	City of Charlotte	Mecklenburg	02/12/2018	Not Compliant	02/12/2018	Other Violation	Violation detected during inspection	Laboratory
Mooresville	NC0083887	4	Charlotte Douglas International Airport	City of Charlotte	Mecklenburg	02/12/2018	Not Compliant	02/12/2018	Other Violation	Violation detected during inspection	Record Keeping
Asheville	NC0085952	5	Candler Travel Center	T A Operating LLC	Buncombe	01/24/2018	Not Compliant	01/24/2018	Other Violation	Violation detected during inspection	Disinfection-Tablet
Asheville	NC0085952	5	Candler Travel Center	T A Operating LLC	Buncombe	01/24/2018	Not Compliant	01/24/2018	Other Violation	Violation detected during inspection	Effluent Sampling
Asheville Asheville	NC0085952 NC0085952	5 5	Candler Travel Center Candler Travel Center	T A Operating LLC T A Operating LLC	Buncombe Buncombe	01/24/2018 01/24/2018	Not Compliant Not Compliant	01/24/2018 01/24/2018		Violation detected during inspection Violation detected during inspection	Effluent Sampling Filtration (High Rate Tertiary)
Asheville Winston-Salem Winston-Salem	NC0085952 NC0087980 NC0087980	5 4 4	Candler Travel Center Pine Hall Elementary School WWTP Pine Hall Elementary School WWTP	T A Operating LLC Stokes County Schools Stokes County Schools	Buncombe Stokes Stokes	01/24/2018 01/30/2018 01/30/2018	Not Compliant Not Compliant Not Compliant	01/24/2018 01/30/2018 01/30/2018	Other Violation	Violation detected during inspection Violation detected during inspection Violation detected during inspection	Filtration (High Rate Tertiary) Flow Measurement - Influent Flow Measurement - Influent

Winston-Salem	NC0087980	4	Pine Hall Elementary School	Stokes County Schools	Stokes	01/30/2018	Not Compliant	01/30/2018	Other Violation	Violation detected during inspection	Laboratory
Winston-Salem	NC0087980	4	WWTP Pine Hall Elementary School WWTP	Stokes County Schools	Stokes	01/30/2018	Not Compliant	01/30/2018	Other Violation	Violation detected during inspection	Laboratory
Winston-Salem	NC0087980	4	Pine Hall Elementary School WWTP	Stokes County Schools	Stokes	01/30/2018	Not Compliant	01/30/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Winston-Salem	NC0087980	4	Pine Hall Elementary School WWTP	Stokes County Schools	Stokes	01/30/2018	Not Compliant	01/30/2018	Other Violation	Violation detected during inspection	Records/Reports
Raleigh	NC0088137	3	Raleigh Convention Center	City of Raleigh	Wake	12/13/2017	Not Compliant	12/13/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Raleigh	NC0088137	3	Raleigh Convention Center	City of Raleigh	Wake	12/13/2017	Not Compliant	12/13/2017	Other Violation	Violation detected during inspection	Records/Reports
Winston-Salem	NC0088749	2	Lissara WWTP	Lissara Partners LLC	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Record Keeping
Winston-Salem	NC0088749	2	Lissara WWTP	Lissara Partners LLC	Forsyth	06/05/2018	Not Compliant	06/05/2018	Other Violation	Violation detected during inspection	Standby Power
Asheville	NC0089095	2	High Vista Falls WWTP	A&D Water Service Inc	Henderson	08/24/2017	Not Compliant	08/24/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Mooresville	NC0089206	2	Church Street remediation site	Plaze Incorporated	Mecklenburg	06/06/2018	Not Compliant	06/06/2018	Other Violation	Violation detected during inspection	Flow Measurement - Influent
Mooresville	NC0089206	2	Church Street remediation site	Plaze Incorporated	Mecklenburg	06/06/2018	Not Compliant	06/06/2018	Other Violation	Violation detected during inspection	Operations & Maintenance
Wilmington	NCG500094	5	Currie Mill	Northwest Hardwoods LLC	Pender	08/23/2017	Not Compliant	08/23/2017	Other Violation	Violation detected during inspection	Record Keeping
Wilmington	NCG500149	5	Duplin General Hospital - Kenansville	Duplin General Hospital Inc	Duplin	12/14/2017	Not Compliant	12/14/2017	Other Violation	Violation detected during inspection	Records/Reports
Mooresville	NCG500214	5	Pharr I-85 Plant	Pharr Yarns LLC	Gaston	04/11/2018	Not Compliant	04/11/2018	Other Violation	Violation detected during inspection	Record Keeping
Mooresville	NCG500221	5	IMC-MetalsAmerica, LLC	I M C-Metalsamerica LLC	Cleveland	11/02/2017	Not Compliant	11/02/2017	Other Violation	Violation detected during inspection	Effluent Pipe
Mooresville	NCG500221	5	IMC-MetalsAmerica, LLC	I M C-Metalsamerica LLC	Cleveland	11/02/2017	Not Compliant	11/02/2017	Other Violation	Violation detected during inspection	Record Keeping
Mooresville	NCG500604	5	Linde LLC	Linde LLC	Cabarrus	11/16/2017	Not Compliant	11/16/2017	Other Violation	Violation detected during inspection	Effluent/Receiving Waters
Mooresville	NCG500653	3	Shelby Feed Mill	Case Farms LLC	Cleveland	10/02/2017	Not Compliant	10/02/2017	Other Violation	Violation detected during inspection	Effluent Pipe
Mooresville	NCG500653	3	Shelby Feed Mill	Case Farms LLC	Cleveland	10/02/2017	Not Compliant	10/02/2017	Other Violation	Violation detected during inspection	Record Keeping
Raleigh	NCG500656	3	Louisburg Finishing Mill	Pruitt Lumber Company Inc	Franklin	08/29/2017	Not Compliant	08/29/2017	Other Violation	Violation detected during inspection	Effluent Sampling
Raleigh	NCG510543	2	Allen's Exxon remediation site	Paragon Environmental Consultants Inc	Orange	06/20/2018	Not Compliant	06/20/2018	Other Violation	Violation detected during inspection	Permit
Mooresville	NCG550065	5	1117 New Prospect Church Road	Roger Dixon	Cleveland	08/30/2017	Not Compliant	08/30/2017	Other Violation	Violation detected during inspection	Record Keeping
Winston-Salem	NCG550709	5	NC Highway 65 Apartments	Dennis Bracy	Stokes	09/12/2017	Not Compliant	09/12/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Winston-Salem	NCG550709	5	NC Highway 65 Apartments	Dennis Bracy	Stokes	09/12/2017	Not Compliant	09/12/2017	Other Violation	Violation detected during inspection	Sand Filters (Low rate)
Raleigh	NCG550740	5	935 Old Oxford Road	Floyd Fogleman	Durham	02/01/2018	Not Compliant	02/01/2018	Other Violation	Violation detected during inspection	Disinfection-Tablet
Raleigh	NCG550793	5	1112 Infinity Road	Leon Hudgins	Durham	06/14/2018	Not Compliant	06/14/2018		Violation detected during inspection	Operations & Maintenance
Raleigh	NCG550911	4	5642 Graham-Hobgood Road	Mary Smith	Granville	02/20/2018	Not Compliant	02/20/2018	Other Violation	Violation detected during inspection	Other
Raleigh	NCG550911	4	5642 Graham-Hobgood Road	Mary Smith	Granville	02/20/2018	Not Compliant	02/20/2018	Other Violation	Violation detected during inspection	Other
Raleigh	NCG551111	5	2125 E Geer St	First Pentecostal Church of Durham	Durham	09/07/2017	Not Compliant	09/07/2017	Other Violation	Violation detected during inspection	Operations & Maintenance
Raleigh	NCG551111	5	2125 E Geer St	First Pentecostal Church of Durham	Durham	09/07/2017	Not Compliant	09/07/2017	Other Violation	Violation detected during inspection	Operations & Maintenance

Raleigh	NCG551111	5	2125 E Geer St	First Pentecostal Church of Durham	Durham	09/07/2017	Not Compliant	09/07/2017	Other Violation Violation detected during inspection	Permit
Raleigh	NCG551223	4	6132 Knightdale Boulevard	Donna Fowler / Eagle's	Wake	12/14/2017	Not Compliant	12/14/2017	Other Violation Violation detected during inspection	Other
Raleigh	NCG551391	4	402 Sandlewood Drive	Express Inc Dungee Taylor	Durham	10/25/2017	Not Compliant	10/25/2017	Other Violation Violation detected during inspection	Operations & Maintenance
Raleigh	NCG551391	4	402 Sandlewood Drive	Dungee Taylor	Durham	10/25/2017	Not Compliant	10/25/2017	Other Violation Violation detected during inspection	Operations & Maintenance
Raleigh	NCG551391	4	402 Sandlewood Drive	Dungee Taylor	Durham	10/25/2017	Not Compliant	10/25/2017	Other Violation Violation detected during inspection	Operations & Maintenance
Raleigh	NCG551391	4	402 Sandlewood Drive	Dungee Taylor	Durham	10/25/2017	Not Compliant	10/25/2017	Other Violation Violation detected during inspection	Operations & Maintenance
Raleigh	NCG551426	3	2320 East Club Boulevard	M M Fowler Inc	Durham	01/25/2018	Not Compliant	01/25/2018	Other Violation Violation detected during inspection	Operations & Maintenance
Raleigh	NCG551475	3	Handee Hugo #96	United Energy Inc	Wake	12/14/2017	Not Compliant	12/14/2017	Other Violation Violation detected during inspection	Other
Raleigh	NCG551497	3	2924 Cheek Road	Charles Ayoub	Durham	05/15/2018	Not Compliant	05/15/2018	Other Violation Violation detected during inspection	Permit
Raleigh	NCG551502	3	6206 Old Kemp Road	Ernest Briggs	Durham	01/22/2018	Not Compliant	01/22/2018	Other Violation Violation detected during inspection	Compliance Schedules
Raleigh	NCG551502	3	6206 Old Kemp Road	Ernest Briggs	Durham	01/22/2018	Not Compliant	01/22/2018	Other Violation Violation detected during inspection	Effluent/Receiving Waters
Raleigh	NCG551502	3	6206 Old Kemp Road	Ernest Briggs	Durham	01/22/2018	Not Compliant	01/22/2018	Other Violation Violation detected during inspection	Effluent/Receiving Waters
Raleigh	NCG551502	3	6206 Old Kemp Road	Ernest Briggs	Durham	01/22/2018	Not Compliant	01/22/2018	Other Violation Violation detected during inspection	Operations & Maintenance
Raleigh	NCG551502	3	6206 Old Kemp Road	Ernest Briggs	Durham	01/22/2018	Not Compliant	01/22/2018	Other Violation Violation detected during inspection	Operations & Maintenance
Raleigh	NCG551502	3	6206 Old Kemp Road	Ernest Briggs	Durham	01/22/2018	Not Compliant	01/22/2018	Other Violation Violation detected during inspection	Operations & Maintenance
Mooresville	NCG590004	1	Cleveland County WTP	Cleveland County Water	Cleveland	04/10/2018	Not Compliant	04/10/2018	Other Violation Violation detected during inspection	Effluent Sampling
Mooresville	NCG590004	1	Cleveland County WTP	Cleveland County Water	Cleveland	04/10/2018	Not Compliant	04/10/2018	Other Violation Violation detected during inspection	Record Keeping

VIOLATION ACTION	VIOLATION COMMENT	NOD CASE	NOD DATE	NOV CASE	NOV LETTER DATE	CPA CASE	CPA LETTER DATE	PENALTY AMOUNT	DAMAGES	ENFORCEMENT COSTS	TOTAL PENALTIES	PENALTY WAIVED DATE
Proceed to NOV	Significant rust and decay of structures, as well as excessive solids in the clarifier discharge troughs were observed.			NOV-2018-PC-0073								
No Action, BPJ	See summary.											
No Action, BPJ	See summary.											
No Action, BPJ	See summary.			NOV-2018-PC-0073								
Proceed to NOV Proceed to NOV	. Wairs absorved are severely decayed. Excessive solids were			NOV-2018-PC-0073								
No Action, BPJ	Weirs observed are severely decayed. Excessive solids were present in the perimeter discharge trough. Units are covered restricting proper inspection. Weirs observed are severely decayed. Excessive solids were			NOV-2018-PC-00/3								
110 / 101.011, 51.5	present in the perimeter discharge trough. Units are covered restricting proper inspection.											
Proceed to NOV	Failure to properly operate and maintain all facilities and systems of treatment and control.			NOV-2018-PC-0005	01/12/2018							
Proceed to NOV	Failure of the ORC to meet the minimum treatment plant			NOV-2018-PC-0005	01/12/2018							
Proceed to NOV	Failure to minimize or prevent any discharge in violation of the			NOV-2018-PC-0005	01/12/2018							
Proceed to NOV	subect permit. Failure to pay the annual administering and compliance			NOV-2018-PC-0005	01/12/2018							
Dragged to NOV	monitoring fee for years 2011 and 2017.			NOV 2019 DC 0005	04 /12 /2010							
Proceed to NOV Proceed to NOV	Failure to restrict public access to the treatment facilities. Failure to submit the Implementation Plan for Elimination of			NOV-2018-PC-0005 NOV-2018-PC-0005	01/12/2018 01/12/2018							
Proceed to NOV	Discharge as required by permit condition A. (5.).			NOV-2018-FC-0003	01/12/2018							
No Action, BPJ	ORC did not have a copy of the current permit with him.											
Proceed to NOD	ORC pumps water from the aeration basin to the clarifier when discharging. Only 1 (of 2) are in use. This clarifier had vegetation growing in the outermost ring, corrosion	NOD-2017-PC-0215	07/27/2017									
Proceed to NOV	completely penetrating the center ring, and weir blockage. Non-report of a spill			NOV-2017-DV-0288	11/13/2017							
Proceed to NOV	WQS violation resulting from spill			NOV-2018-SS-0020	06/01/2018							
Proceed to NOV	Split grab sample result for TSS was reported as 53 mg/l by the Asheville Regional Office Laboratory. This exceeds the permit			NOV-2018-PC-0083	03/13/2018							
Proceed to NOV	daily maximum limit of 45 mg/l Excessive amount of foam was observed.			NOV-2018-PC-0124	04/12/2018							
Proceed to NOV	Sampler tubing appeared to be dirty.			NOV-2018-PC-0124	04/12/2018							
Proceed to NOV	The flow meter is past due for calibration. The flow meter was due for calibration on December 14, 2017.			NOV-2018-PC-0124	04/12/2018							
Proceed to NOV	At the time of the inspection an excessive amount of foam was			NOV-2018-PC-0124	04/12/2018							
Proceed to NOV	observed in the treatment units including at the sampling ORC logs must be more detailed and include maintenance work done, including the date equipment was taken offline			NOV-2018-PC-0124	04/12/2018							
Proceed to NOV	and date the equipment was fixed and returned to service. At the time of the inspection short-circuiting was evident. Additionally, the clarifier trough was full of debris.			NOV-2018-PC-0124	04/12/2018							
Proceed to NOV	The contents in aeration basin #1 were not being properly mixed and aerated due to two inoperable aerators.			NOV-2018-PC-0081	03/08/2018							
Proceed to NOV	Lint screenings were not being properly contained and were observed adjacent to a stormwater drain.			NOV-2018-PC-0081	03/08/2018							
Proceed to NOV	Influent sampler was not being properly calibrated and not collecting representative samples, pending production run.			NOV-2018-PC-0081	03/08/2018							
Proceed to NOV	The pH meter was not checked with a standard buffer following calibration. pH buffers were being reused for daily			NOV-2018-PC-0081	03/08/2018							
	calibrations. Sample refrigerator temperature was not being measured during days used for storage. DO meter was not being properly verified against a standardized chart.											

Proceed to NOV	An AST (petroleum) was being stored on top of the influent			NOV-2018-PC-0081	03/08/2018						
1100000 101101	grating system.			1107 2010 1 0 0001	00,00,2010						
Proceed to NOV	No influent, upstream, and downstream monitoring was			NOV-2018-PC-0081	03/08/2018						
	performed during the week of 11/19/17 and 12/24/17. The										
	WWTP was not visited (on two days) by the ORC and/or										
Proceed to NOV	Backup ORC during the week of 12/24/17. The facility failed to report a bypass of the clarifier that led to			NOV-2018-PC-0081	03/08/2018						
	effluent limit violations during first week of January 2018.										
Proceed to NOD	The temperature of the thermometer inside the Effluent	NOD-2017-PC-0206	07/10/2017								
	composite sampler, during several sampling events, was										
	higher than 6.0 degrees Celsius. The subject permit requires effluent composite and grab samples.										
Proceed to NOD	The temperature of the thermometer inside the influent	NOD-2017-PC-0206	07/10/2017								
	composite sampler, during several sampling events, was										
Proceed to NOV	higher than 6.0 degrees Celsius. Flow proportional sampling is not conducted as required.			NOV-2018-PC-0244	07/18/2018						
Proceed to NOV	Sampling is not flow proportional as required.			NOV-2018-PC-0244 NOV-2018-PC-0244	07/18/2018						
Proceed to NOV	Screenings, debris on the ground at arc bar, several treatment			NOV-2018-PC-0244	07/18/2018						
Troceed to NOV	units were not operable, sludge on the ground			1404 2010 1 6 0244	07/10/2010						
Proceed to NOV	Freeboard levels not recorded daily as required. Annual			NOV-2018-PC-0244	07/18/2018						
	report not available.				07/10/2012						
Proceed to NOV	Annual report not available.			NOV-2018-PC-0244	07/18/2018						
Proceed to NOV	LTMP and IUP minimum detection levels for several parameters were not met during LTMP sampling events.			NOV-2017-PC-0512	07/28/2017						
Proceed to NOV	Monitoring violations were not enforced according to ERP.			NOV-2017-PC-0512	07/28/2017						
Proceed to NOV	The TOMP for Steag was available during the inspection.			NOV-2017-PC-0512	07/28/2017						
Proceed to NOD	Mr. Wood said that the alarms did not work and he did not	NOD-2018-PC-0148									
	know the cause.										
Proceed to NOD	One of the clarifiers was broken but was still being used for treatment. Black sludge was bubbling to the surface and in	NOD-2018-PC-0148									
	some parts flowing over the weir.										
Proceed to Enforce	ement Signficant solids from the bar screens were present on the					PC-2017-0043	11/01/2017	\$1,750.00	\$1	126.81	\$1,876.81
	ground surrounding the screening unit during the inspection.										
	The ORC reports difficulty in efficiently having the screens										
	transfer solids to the dumpster to disposal, this requires										
	additional manual effort from the operators. The presence of screened solids outside the screen unit and dumpster could										
	generate a nuicance and/or health hazard										
Proceed to Enforce	rement Signficant solids from the bar screens were present on the			NOV-2017-PC-0645	10/06/2017						
	ground surrounding the screening unit during the inspection. The ORC reports difficulty in efficiently having the screens										
	transfer solids to the dumpster to disposal, this requires										
	additional manual effort from the operators. The presence of										
	screened solids outside the screen unit and dumpster could										
Proceed to Enforce	rement A high level of solids were present in the contact chamber					PC-2017-0043	11/01/2017	\$1,750.00	\$1	126.81	\$1,876.81
	during the inspection.						,,	<i>+</i> = <i>,</i> · · · · · · · · · · · · · · · · · · ·	*		, -, -, -, -, -, -, -, -, -, -, -, -, -,
Proceed to Enforce	ement A high level of solids were present in the contact chamber			NOV-2017-PC-0645	10/06/2017						
Proceed to Enforce	during the inspection. The sement Housekeeping at the facility was poor. Animal waste (from					PC-2017-0043	11/01/2017	\$1,750.00	ė,	126.81	\$1,876.81
Proceed to Emore	farms animal present on the facility) was present in walking					PC-2017-0043	11/01/2017	\$1,750.00	Ş .	120.01	\$1,670.61
	and driving areas. The ORC reported that the last 3 years for										
	pretreatment records had been destroyed by vermin. Some										
	improvements have been made in the chemical feed area, but										
Proceed to Enforce	areas of incomplete construction and trip hazards still exist tement. Housekeeping at the facility was poor. Animal waste (from			NOV-2017-PC-0645	10/06/2017						
	farms animal present on the facility) was present in walking				• • -						
	and driving areas. The ORC reported that the last 3 years for										
	pretreatment records had been destroyed by vermin. Some										
	improvements have been made in the chemical feed area, but areas of incomplete construction and trip hazards still exist										
Proceed to Enforce	ement No hard copy or electronic records available for past 3 years					PC-2017-0042	11/01/2017	\$100.00	\$1	126.81	\$226.81
	due to inadequate storage conditions.										

Pi	roceed to Enforcement	No hard copy or electronic records available for past 3 years			NOV-2017-PC-0643	10/06/2017					
Pı		due to inadequate storage conditions. Signficant solids were noted in the SBRs, and downstream as					PC-2017-0043	11/01/2017	\$1,750.00	\$126.81	\$1,876.81
Di		far as the chlorine contact chamber during the inspection. Signficant solids were noted in the SBRs, and downstream as			NOV-2017-PC-0645	10/06/2017					
	o Action, BPJ	far as the chlorine contact chamber during the inspection. The ORC reports adequate standby power, but also reports the lightning strikes cause frequent shutdown of critical pieces			NOV-2017-FC-0043	10/00/2017					
Pi	roceed to NOD	of equipment. Both secondary clarifiers were operational and in service. Both clarifiers required maintenance, at the time of the inspection	NOD-2018-PC-0025	02/19/2018							
		the clarifier weir had excessive algae growth and small									
Pi	roceed to Enforcement	conecting sections were missing allowing bypass. The WWTP is inadequate for solids handling, partly due to inadequate sludge storage. SEE SUMMARY FOR MORE					LV-2017-0269	09/07/2017	\$4,350.00	\$160.31	\$4,510.31
Pi	roceed to Enforcement	The WWTP is inadequate for solids handling, partly due to inadequate sludge storage. SEE SUMMARY FOR MORE			NOV-2017-LV-0541	08/11/2017					
N	o Action, BPJ	Reportedly Cl gas is fed proportional to flow and is controlled									
		by the ultrasonic flow meter located at the aerated contact chamber. NOTE: both contact chambers are aerated.					LV 2047 0260	00/07/2047	44.250.00	4450.24	Ć4 540 24
Pi		Currently sampling on 30 min. time intervals with 150 mL per sample event.					LV-2017-0269	09/07/2017	\$4,350.00	\$160.31	\$4,510.31
Pi		Currently sampling on 30 min. time intervals with 150 mL per sample event.			NOV-2017-LV-0541	08/11/2017					
Pi	roceed to Enforcement	Flow meter serving Channel #2 needs replacing, and the flow					LV-2017-0269	09/07/2017	\$4,350.00	\$160.31	\$4,510.31
		meter serving Channel #3 is recommended for replacing also. SEE SUMMARY FOR MORE DETAILS.									
Pi	roceed to Enforcement	Flow meter serving Channel #2 needs replacing, and the flow			NOV-2017-LV-0541	08/11/2017					
		meter serving Channel #3 is recommended for replacing also. SEE SUMMARY FOR MORE DETAILS.									
Pi		No residuals solids removal records for 2017 present.					LV-2017-0269	09/07/2017	\$4,350.00	\$160.31	\$4,510.31
		No residuals solids removal records for 2017 present.			NOV-2017-LV-0541	08/11/2017					
Pi		Failed to require SIU monitoring, failed to monitor and inspect, failed to take appropriate enforcement action			NOV-2018-PC-0101	03/27/2018					
Pi	roceed to NOD	Permit Standard Conditions, Section D.9, requiring	NOD-2018-PC-0192								
Pi	roceed to NOV	enforcement actions consistent with the enforcement Bypass with discharge to surface waters.			NOV-2018-PC-0020						
		DWR did not recieve a written report within the required 5-			NOV-2018-PC-0020						
Di		day report period. Failed to take enforcement action as specified in the ERP.	NOD-2018-PC-0206								
		The lagoon has not been maintained. There is woody	NOD-2018-F C-0200		NOV-2018-PC-0184	05/25/2018					
		vegetation, animal burrows, and erosion on the side									
		slopes/dikes. The outfall structure is deteriorating and is in need of maintenance the access structure seems unstable.									
		The ORC noted that no wastewater discharges to the lagoon									
		have occurred while on site. The permittee should verify that									
Pi	roceed to NOV	the wastewater from the facility is discharging to the The lagoon has not been maintained. There is woody			NOV-2018-PC-0184	05/25/2018					
		vegetation, animal burrows, and erosion on the side									
		slopes/dikes. The outfall structure, which contains the chlorine disinfection box is deteriorating and needs									
		maintenance the access structure seems unstable. The facility									
		has not discharged in more than 14 years, the permitee should									
		conduct an engineering evaluation of the sewer system, including the sewage path of influent sewer to the pond,									
		sludge level in the pond, stability of the pond banks and									
		evaluate if the outfall structure (an older report suggests that									
		the reason for non-discharge is a leak in the structure below				/					
Pi		The subject permit is for a stabilization lagoon followed by chlorine disinfection. the chlorine disinfection is in poor shape and could not be reached to maintain.			NOV-2018-PC-0184	05/25/2018					

Proceed to NOV	at the time of the inspection both blower/motor units were not operational and the plant was running on undersized			NOV-2017-PC-0445	07/07/2017
Proceed to NOV	backup blower. at the time of the inspection both blower/motor units were not operational and the plant was running on undersized			NOV-2017-PC-0445	07/07/2017
Proceed to NOD	backup blower. The City failed to initiate enforcement according to Division	NOD-2017-PC-0217	08/03/2017		
Proceed to NOD	approved ERP for a SIU's reporting violation in April 2017. Mr. Bani said that the effluent composite sampler takes 1 $^{\sim}$ 120 ml aliquot every 15 minutes. Aliquot volume was not verified	NOD-2018-PC-0034	03/01/2018		
No Action, BPJ	during the inspection. 3 of 4 influent pumps are in service.				
Proceed to NOD	Mr. Bani said that the onsite generator was capable of	NOD-2018-PC-0034	03/01/2018		
	powering the entire plant except the effluent pumps. He said				
Proceed to NOD	they are hoping to upgrade the emergency power source. Land application is the primary disposal of the bio-solids however, the drying beds are used during emergency	NOD-2018-PC-0154	04/20/2018		
	situations when wet weather prevents land application (Last				
	used on December 2017). The drying beds are also periodically				
	used for the disposal of landfill leachate, tank cleaning/pump				
	station maintenance, and septage (infrequent). The drying bed sections currently being used contained excessive vegetation				
	(including several trees) and require extensive maintenance. If				
	the facility continues to periodically use the drying beds, then				
	the previously rehabbed sections should be placed into				
	operation. Please be advised that the subject permit requires				
	the facility be properly operated and maintained at all times [NPDES Permit Standard Condition Reference: Part II, Section				
	C(2) – Proper Operation and Maintenance]. If the drying beds				
	are no longer needed, they could be removed from the permit				
Proceed to NOD	The influent flow meter is not operational during times of high storm flows.	NOD-2018-PC-0033			
Proceed to NOV	Two of the air diffusers are not working.			NOV-2018-PC-0041	
Proceed to NOV	Bar screen rags were not well contained.			NOV-2018-PC-0041	
Proceed to NOV	Lots of growth/algae in effluent weir chamber.			NOV-2018-PC-0041	
Proceed to NOV	Return lines are missing flaps that keep sludge flow directed into the aeration tank.			NOV-2018-PC-0041	
Proceed to NOV	Very high solids level in the aeration tank. Settleable solids			NOV-2018-PC-0041	
Proceed to NOV	were at 89%. Center well was full of floating solids.			NOV-2018-PC-0041	
Proceed to NOV	Permit Condition Part II. Section C (1) requires an ORC			NOV-2017-PC-0684	10/30/2017
	designation form be submitted within 120 days of a vacancy.				-,, -
Proceed to NOV	This is a repeat deficiency that was first addressed in the CEI Unequal discharge rates observed between Clarifier 1 and			NOV-2017-PC-0684	10/30/2017
Proceed to NOD	Clarifer 2, and floating solids observed in Clarifier 2 DO is low, about 0.8 However there is more airation after the	NOD-2018-PC-0212	07/25/2018		
Proceed to NOD	disinfection step. UV system is down. Using CI until the machine is fixed	NOD-2018-PC-0212	07/25/2018		
Proceed to NOD	Carolina Classics Catfish limit violations in July 2017 for Oil and Grease and December 2017 limit violation for flow. CMSD	NOD-2018-PC-0167	05/11/2018		
	needs to follow ERP for IUP permit violations				
Proceed to NOD	Weyerhaeuser limit violation in February 2017 for BOD. CMSD	NOD-2018-PC-0167	05/11/2018		
Proceed to NOV	needs to follow ERP for IUP permit violations Do was low, around 0.8			NOV-2018-PC-0234	07/25/2018
Proceed to NOV	One UV bulb was out, while one was working. ORC took a fecal sample and says they are still in compliance.			NOV-2018-PC-0234	07/25/2018
No Action, BPJ	Permit on site had expired. Talked to Water Quality Labs and they had submitted for a new permit but have not recieved				
	the new one yet. The plant is on private property but not fenced off. Doug. the property owner. is around and keeps				

Proceed to NOV	Bench sheet data does not match DMR on 3/21/18 and			NOV-2018-PC-0234	07/25/2018					
n li Nov	3/28/2018. Both 14 on bench sheet but reported as 7.			NOV 2047 DO 2002	00/00/0047					
Proceed to NOV	The facility has 2 treatment tracks, one is active and the other is inactive. The ORC indicated that there was leakage from the			NOV-2017-PC-0602	09/08/2017					
	septic tanks into the inactive Track. The inactive treatment									
	rack must be properly sealed. Three diffusers need to be									
	replaced in the active aeration basin.									
Proceed to NOV	Records for the flow meter calibration were unavailable for			NOV-2017-PC-0602	09/08/2017					
	review during the inspection. Flow meter chart recorder was out of paper and has not been recording flow.									
Proceed to NOV	At the time of the inspection the facility needed the			NOV-2017-PC-0602	09/08/2017					
	following items to be repaired/investigated (see attached									
Proceed to NOV	No records were available for review for the period of august 1			NOV-2017-PC-0602	09/08/2017					
Proceed to Enforcemen	,2014 - august 1, 2017. t No ORC or backup ORC has been designated for the subject					PC-2018-0004	02/16/2018	\$3,000.00	\$209.77	7 \$3,209.77
Froceed to Emorcemen	facility. ORC has resigned December 1, 2017, since than the					FC-2018-0004	02/10/2018	\$3,000.00	\$209.77	γ3,203.77
	facillity has not designated an ORC.									
Proceed to Enforcemen	t No ORC or backup ORC has been designated for the subject			NOV-2017-PC-0712	12/12/2017					
	facility. ORC has resigned December 1, 2017, since than the									
Proceed to Enforcemen	facillity has not designated an ORC. t No ORC or backup ORC has been designated for the subject					PC-2018-0004	02/16/2018	\$3,000.00	\$209.77	7 \$3,209.77
Froceed to Emorcemen	facility. ORC has resigned December 1, 2017, since than the					FC-2018-0004	02/10/2018	\$3,000.00	\$209.77	γ3,203.77
	facillity has not designated an ORC.									
Proceed to Enforcemen	t No ORC or backup ORC has been designated for the subject			NOV-2017-PC-0712	12/12/2017					
	facility. ORC has resigned December 1, 2017, since than the									
Proceed to NOV	facillity has not designated an ORC. Flow meter had not been calibrated in over a year			NOV-2018-PC-0030	02/16/2018					
Trocced to Nov	now meter had not been cambrated in over a year			1101 2010 1 0 0030	02/10/2010					
Proceed to NOV	ORC log were not avilable for review for the period of August			NOV-2018-PC-0030	02/16/2018					
	2014 - August 2017. At the time of theinspection the following									
	operational issues were noted: Untreated wastewater had									
	accumulated on the ground beside the leaking septic tanks.									
	The microbial population in the operable aeration basin									
Proceed to NOV	No recoreds were avilable for review for the period of August			NOV-2018-PC-0030	02/16/2018					
	1, 2014 - August 1, 2017. At the time of the inspection the									
	facillity has not submitted EDMR for the months of August									
Proceed to NOV	2017 - November 2017. Septic tanks had cracks, waste water leached has was evident			NOV-2018-PC-0030	02/16/2018					
	by the untreated wastewater that had accumulated on the									
	ground beside the leaking septic tanks.									
Proceed to NOV	Tablet de-chlorinator tube was placed in chamber beyond the			NOV-2017-PC-0651						
Proceed to NOV	V-notch weir. Contact chamber had excessive solids.			NOV-2017-PC-0651						
Proceed to NOV	Excessive solids were being discharged into the receiving			NOV-2017-PC-0651						
Donate NOV	waters.			NOV 2017 DC 0651						
Proceed to NOV	Split sample performed. Inspector sample results were non- compliant with the Daily Maximum Effluent Limits for Fecal			NOV-2017-PC-0651						
	Coliform, TSS and BOD. Sample collection in chamber beyond									
	V-notch weir.									
Proceed to NOV	Heavy solids throughout plant. Log book did not indicate			NOV-2017-PC-0651						
Dragged to NOV	process controls performed.			NOV 2017 DC 0651						
Proceed to NOV	Solids were surging over the weirs. Blanket apparent at ~1' from surface. Overflow had excessive solids.			NOV-2017-PC-0651						
Proceed to NOD	Failure to pay annual administering and compliance	NOD-2018-PC-0160	04/26/2018							
	monitoring fee within 30 day following billing by Division.									
Proceed to NOV	The UV disinfection system was inoperable with one of the			NOV-2018-PC-0086						
	two bulbs blown, and the additional backup bulb onsite had									
	not been installed within three (3) davs since the system									

Proceed to NOV	The UV system was down and not operating. When ORC was questioned, the UV system apparently went down sometime during the past weekend's storm event when one of the two working bulbs blew. The Washington Regional Office was not notified of this equipment failure nor of the bypass of the UV treatment unit. There was only one extra UV bulb onsite, however it was not yet installed. The ORC was directed to			NOV-2018-PC-0086	
No Action, BPJ	UV System had no spare bulbs and the intensity meter was in the red reading low. Fecal count results <1 #/100 ml DMR February. System appeared to be disinfecting.				
No Action, BPJ	In line water meter is used .				
Proceed to NOV	A pump with a by-pass hose is connected to discharge line. Grease is visable on top of tank. The pump station was not			NOV-2018-PC-0131	04/23/2018
No Action, BPJ	locked and no signage tank was open. Max O'Neal is the ORC and Henry Boyd is the back-up ORC. The copy of NPDES Permit needs to keep on site. Three years				
No Action, BPJ	of DMRs need to be availible during inspections. Max O'Neal is the ORC and Henry Boyd is the back-up ORC. The copy of NPDES Permit needs to keep on site. Three years				
Proceed to NOD	of DMRs need to be availible during inspections. The composite sampler was not collecting samples over a 24-hr. period.	NOD-2017-PC-0249	11/07/2017		
Proceed to NOD	The flume throat and head mesurement locations were not consistent with the standard flume dimensions.	NOD-2017-PC-0249	11/07/2017		
Proceed to NOD	The grit removal system was not operational and has not been consistently operational for several years.	NOD-2017-PC-0249	11/07/2017		
Proceed to NOD	The sampler was not collecting 100 ml. per aliquot.	NOD-2017-PC-0249	11/07/2017		
Proceed to NOD	All dissolved oxygen meter calibrations (instream monitoring)	NOD-2017-PC-0249	11/07/2017		
	were not being documented.				
Proceed to NOV	The permit requires composite sampling but the ORC has only			NOV-2017-PC-0561	08/23/2017
No Action, BPJ	been taking grab samples. Past inspection reports have recommended adding a bar				
No Action, BPJ	screen at the plant. Operator explained that bar screens are present at the collection system pump stations. Filters had vegetation growing in them. The vegetation needs to be removed, and anthacite and sand filter media should be				
No Action, BPJ	inspected and replaced if necessary. Permit includes backup generator. The onsite generator is not				
Proceed to NOV	operational. On-site Generator is not operational, no back-up generator present. The permit lists a back-up generator as a systen			NOV-2017-PC-0699	11/28/2017
Proceed to NOV	Dechlorination was being provided prior to the chlorine contact chamber.			NOV-2018-PC-0121	04/11/2018
Proceed to NOV	The tablet chlorinator was not being used and dechlorination was being performed prior to the chlorine contact chamber.			NOV-2018-PC-0121	04/11/2018
Proceed to NOV	Blower/motor units needed replacement, No preventive maintenance activities have been initiated on the blower/motor units including no oil changes, air filter			NOV-2018-PC-0121	04/11/2018
	replacement, etc. Excessive vegetation was observed inside the treatment facility fence. Chlorination and dechlorination				
Proceed to NOV	systems were not being properly operated The permittee did not maintain three years of permit-required			NOV-2018-PC-0121	04/11/2018
Proceed to NOV	reports and monitoring data. At the time of the inspection it was discovered that the facility has not conducted quarterly hardness sampling (Effluent and			NOV-2018-PC-0023	01/31/2018
	upstream) for the quarter ending in September 2017 and hardness sampling (upstream) for the quarter ending in December 2017. Hardness sampling was added to the facility				
Proceed to NOV	monitoring requirements on the recent permit effective Broken distribution line.			NOV-2018-PC-0038	

Proceed to NOV	Excessive vegetation on the sand filter surface.			NOV-2018-PC-0038	
rocced to NOV	_				
Proceed to NOV	There are 4 distribution lines to the sand filter and it appeared that only one of those was receiving flow. The one line that			NOV-2018-PC-0038	
Proceed to NOV	appeared to be working had a lot of ponding around it. Possibly clogged dosing syphons.			NOV-2018-PC-0038	
	It was noted that solids in digester was very thick and digester				
	was full. WAS is pumped from aerobic digester to drying beds. It as				
	noted at time of inspection that one of the two drying beds				
	was being used to stockpiled dry sludge.				
	It is recommended that the proper laboratory apparatus be used while performing settleability test, either a settlometer				
	and/or 1000 or 2000 mL graduated.				
	RAS-WAS pumps are located in wet well at secondary				
Proceed to NOV	The Town failed to collect influent and effluent samples according to the Division approved STMP. Effluent STMP			NOV-2018-PC-0212	07/03/2018
	results were not reported on the edmrs. The Town failed to				
Proceed to NOV	collect all IUP parameters during the July - December 2017 The UV intensity meter was flashing and reading at 0.8. Unsure			NOV-2018-PC-0231	07/25/2018
	if this was accurate due to the amount of solids being discharged into the stream. Straggler floc was being				
Proceed to NOV	Grab sampling			NOV-2018-PC-0231	07/25/2018
Proceed to NOV	Bench sheet data did not match the reported DMR values for			NOV-2018-PC-0231	07/25/2018
	NH3 on 8/17, 8/24, and 8/29. 8/17 was a single digit mistake				
Proceed to NOV	while the other two were reported at half the amount on the Sludge blanket was 5 to 6 ft which is about half of the depth. This caused solids to flow out of the plant.			NOV-2018-PC-0231	07/25/2018
Proceed to NOD	Dark activated sludge with very little foam, if any, and DO on the low side.	NOD-2018-PC-0207	07/05/2018		
Proceed to NOD	None	NOD-2018-PC-0207	07/05/2018		
Proceed to NOD	No bar screen. Number of septic tanks not specified.	NOD-2018-PC-0207	07/05/2018		
Proceed to NOD	Sludge and septic tank pumping records, as well as all records	NOD-2018-PC-0207	07/05/2018		
Proceed to NOD	prior to arrival of current ORC in August 2017, appear to be Mr. Luther said he does not hold a field certification, and did	NOD-2018-PC-0158			
	not have daily calibration records for pH and DO (saying only				
	that the meter itself, a YSI 55 DO meter, was calibrated				
	annually). He said the chlorine device (Hach DR 2700) is calibrated annually, but he did not have the record with him				
Proceed to NOD	Operator log is not maintained on site.	NOD-2018-PC-0158			
No Action, BPJ	A copy of the permit was not available during the follow up				
Dragged to NOD	inspection. ORC said he takes the downstream sample from essentially the	NOD 2019 DC 0159			
Proceed to NOD	same place as the effluent sampling due to site access issues	NOD-2018-PC-0158			
	and lack of continuous flow in the receiving stream. During the				
	4/13 follow up inspection I verified that the receiving stream				
Proceed to NOV	was not flowing on that day. Please note that not Post-air diffuser was not working at time of inspection and			NOV-2018-PC-0072	03/12/2018
1100000 101101	effluent D.O. was only 3.2 mg/L appeared to have air			1404 2010 1 6 0072	03/12/2010
	blockage. It began working after teh inspection concluded. it				
Proceed to NOV	should be removed and cleaned/repaired. Secondary blower is not operational and needs to be replaced			NOV-2018-PC-0072	03/12/2018
	following failed repair. One blower cannot adequately supply				
	air to AP and noct air diffusor				
Proceed to NOV	air to AB and post-air diffuser. There is signficant corrosion in the plant walls, piping and			NOV-2018-PC-0072	03/12/2018
Proceed to NOV				NOV-2018-PC-0072	03/12/2018
Proceed to NOV Proceed to NOV	There is signficant corrosion in the plant walls, piping and			NOV-2018-PC-0072 NOV-2018-PC-0072	03/12/2018

Proceed to NOV	Low dissolved oxygen and suspended solids. Foam covers a	NOV-2018-PC-0218	
Proceed to NOV	majority of both basins, but more in the northern basin. There is currently no bar screen installed since approximately	NOV-2018-PC-0218	
Proceed to NOV	the end of 2015. It still hasn't been replaced yet. Outfall not accessible due to the overgrowth.	NOV-2018-PC-0218	
Proceed to NOV	None	NOV-2018-FC-0218	
Proceed to NOV	Bar screen missing.	NOV-2018-PC-0218	
Proceed to NOV	None	NOV-2018-PC-0218	
Proceed to NOV	Station is in very poor condition. High-level float/alarm are	NOV-2018-PC-0218	
	inoperable, as they have been in several past inspections. Also,		
	the discharge piping from the station's pumps to the splitter box is inappropriate must be replaced with hardwall piping.		
Proceed to NOV	Sludge records are incomplete or unavailable.	NOV-2018-PC-0218	
Proceed to NOV	Pin floc overflowing the weirs.	NOV-2018-PC-0218	
Proceed to NOV	Bar screen was full of debris, ORC must clean the debris on a	NOV-2017-PC-0724	12/20/2017
	regular basis.		,,
Proceed to NOV	Floor grating was missing throughout most of the facility. a	NOV-2017-PC-0724	12/20/2017
	slipery wood board was used in the aertion basin, clarifier		
	area. At the time of the inspection the wood was slipery and		
	dangerous. All floor grating should be properly installed to		
Due so sel to NOV	ensure the safety of the ORC/operators and DWR staff.	NOV 2010 DC 0075	02/06/2018
Proceed to NOV	Aeration basin diffusers were not operating properly. Diffusers	NOV-2018-PC-0075	03/06/2018
Proceed to NOV	should be examined regularly and repaired/replaced as Bar screen was full of debris. Bar screen Is undersized and is	NOV-2018-PC-0075	03/06/2018
1100000 10 110 1	insufficient to catch the debris of the influent flow. Screening	100 2010 1 0 0075	03/00/2010
	was observed in downstream treatment units.		
Proceed to NOV	sludge was observed in the chlorine chamber.	NOV-2018-PC-0075	03/06/2018
Proceed to NOV	The ORC and staff must ensure that the start date/time and	NOV-2018-PC-0075	03/06/2018
	the end date/time are documented for all future composite		
	sampling events. There was no thermometer in the composite		
	sampler, The sampler's temperature must be measured and		
	documented for each composite sampling event to verify that		
	the samples were being properly preserved at less than or		
	equal to 6.0 degrees Celsius. At the time of the inspection it		
	was evident that the effluent sampler tubing was dirty, and		
	sagging. ORC must start performing and recording Aliquot		
Proceed to NOV	At the time of the inspection the facility appeared to be poorly	NOV-2018-PC-0075	03/06/2018
	maintained (see summary page).		
Proceed to NOV	The data reviewed for the COCs and DMR was inconsistent,	NOV-2018-PC-0075	03/06/2018
	please see table 1 attached to the report. The ORC must begin		
Proceed to NOV	to indicate in the COC the start and finish time of the Secondary clarifier skimmer was not working properly.	NOV-2018-PC-0075	03/06/2018
1100000 10 110 1	Floating sludge was observed in the clarifier. Return pipes	100 2010 1 0 0073	03/00/2010
	were observed to vibrate causing turbulence in the clarifier.		
Proceed to NOV	The gate to the plant is missing and needs to be replaced.	NOV-2017-PC-0562	08/23/2017
No Action, BPJ	Air should be supplied to aerobic digester.		
Due so sel to NOV	Dave on beginning and pleased to a few amount. Dave and debute	NOV 2017 DC 0525	00/00/2017
Proceed to NOV	Bars on barscreen are placed too far apart. Rags and debris accumulating in flow equalization basin.	NOV-2017-PC-0525	08/08/2017
No Action, BPJ	Bars on barscreen are placed too far apart. Rags and debris		
	accumulating in flow equalization basin.		
Proceed to NOV	Effluent sampler should have a thermometer to measure	NOV-2017-PC-0525	08/08/2017
	sample storage temperature. Sample temperature should be		
	equal or less than 6.0 degrees C.		
No Action, BPJ	Effluent sampler should have a thermometer to measure		
	sample storage temperature. Sample temperature should be		
Proceed to NOV	equal or less than 6.0 degrees C. Flow meter not operating at time of inspection.	NOV-2017-PC-0525	08/08/2017
ויזטנבפט נט ואטע	How meter not operating at time of inspection.	INO V-2017-PC-0323	00/00/201/

Proceed to NOV	Rags and debris in roll-away trash bins should be disposed of			NOV-2017-PC-0525	08/08/2017					
	properly in sanitary landfill. Flow meter not operating at time									
No Action, BPJ	of inspection. Effluent was clear with visible suspended solids going over									
,	weirs. Sludge blanket was noted near surface of secondary									
Proceed to Enforcement	t sludge and low DO in creek					PC-2017-0038	12/14/2017	\$13,500.00	\$603.26	\$14,103.26
Proceed to Enforcement	t sludge and low DO in creek			NOV-2017-PC-0457	07/13/2017					
Proceed to NOD	The facility was not equipped with a tablet chlorinator as	NOD-2018-PC-0147	04/12/2018							
Dungan d to NOV	previously approved by the Division via AtC on 12/5/86.			NOV 2017 OV 0001	00/11/2017					
Proceed to NOV	The plant operator was not able to tell the inspectors how the composite sampler was programed, which includes how much			NOV-2017-OV-0001	08/11/2017					
	flow volume is collected with each sample collection within									
	the 24-hour period.									
Proceed to NOV	The nitrate recycle pump was not in operation due to a broken			NOV-2017-OV-0001	08/11/2017					
Proceed to NOV	rail that holds the pump to the wall of the treatment unit. Treatment components not in operation.			NOV-2017-OV-0001	08/11/2017					
Proceed to NOV	Anticipated Noncompliance			NOV-2017-OV-0001	08/11/2017					
Proceed to NOV	Backup operator failed to operate and visit the facility as			NOV-2017-OV-0001	08/11/2017					
Proceed to NOV	The fence surrounding the plant has been cut in 2 different			NOV-2017-OV-0001	08/11/2017					
1100000 10 1000	places compromising the the security of the treatment plant			100 2017 0 0001	00/11/2017					
Proceed to NOV	At the time of the inspection parts of the bar screen were			NOV-2017-PC-0723	12/20/2017					
	missing allowing screening to bypass the bar screen. Bar									
	screen need to be either fixed or replaced, parts of the bar									
	screen are missing allowing screening to bypass the bar									
Proceed to NOV	screen Screenings are disposed by Republic/GDS at the The facility had no safe way to reach the effluent pipe in order			NOV-2017-PC-0723	12/20/2017					
	to collect grab sample. At the time of the inspection the									
	effluent appeared clear with no foam.									
Proceed to NOV	The Flow meter was calibrated on 12/11/2017 but records			NOV-2017-PC-0723	12/20/2017					
	were unavailable to be reviewed at the time of the inspection. Flow meter does not chart the flow.									
Proceed to NOV	At the time of the inspection the following maintenance issues			NOV-2017-PC-0723	12/20/2017					
	were observed: 1) The facility has no source of standby				, ,					
	power. 2) The facility had no safe way to collect grab sample									
	from the effluent pipe. 3) Effluent sampler Lack proper									
	heating in order to maintain temperature above 0 degrees. 4)									
	Skimmer needed to be fixed in the clarifier, floating sludge was									
	evident. 5) Bar screen need to be either fixed or replaced, parts of the bar screen are missing allowing screening to									
	bypass the bar screen. Bar screen need to be either fixed or									
	replaced, parts of the bar screen are missing allowing									
Proceed to NOV	Records reviewed during the inspection were well maintained			NOV-2017-PC-0723	12/20/2017					
1100000 101101	some records requested during the inspection were not			1101 2017 1 0 0723	12, 20, 201,					
	available and were sent to the inspector on a later date.									
	DMRs, COCs Calibration logs and ORC logs were reviewed for									
	January 2017 through September 2017. Facility COCs do not									
Proceed to NOV	At the time of the inspection the clarifier skimmer needed to			NOV-2017-PC-0723	12/20/2017					
	be fixed, floating sludge was evident.				,,,					
Proceed to NOV	Bar screen was not present. ORC stated that it had fallen into			NOV-2017-SP-0023	12/29/2017					
D 1: NOV	bottom of EQ basin			NOV 2247 CD 2222	10/00/0017					
Proceed to NOV	Failure to provide non-compliance notification regarding bar			NOV-2017-SP-0023	12/29/2017					
Proceed to NOV	screen failure. Rotted timber platform atop EQ basin of original plant is			NOV-2017-SP-0023	12/29/2017					
	hazardous and must be removed. A new platform will need to				,,					
	be installed if it is needed to operate the plant.									
Proceed to NOV	Repairs not fully performed, no structural engineering			NOV-2017-SP-0023	12/29/2017					
Proceed to NOV	evaluation performed as required by DWR.			NOV-2018-PC-0178						
Proceed to NOV Proceed to NOV	Leaking pipe at chlorinator. Rusted gratings.			NOV-2018-PC-0178 NOV-2018-PC-0178						
Proceed to NOV	Outfall needs to be located.			NOV-2018-PC-0178						
1 TOCCCO TO NOV	Gardin riceus to be located.			140 V 2010-1 C-01/0						

Dungan and the MOV	TSS areh careala of 150 may/			NOV 2019 DC 0179	
Proceed to NOV Proceed to NOD	TSS grab sample of 150 mg/L The audible alarm at the influent pump station was not	NOD-2018-SP-0001	03/15/2018	NOV-2018-PC-0178	
	functional during the inspection and needs to be replaced as	2020 0: 0002	00, 20, 2020		
Proceed to NOD	soon as possible. It was also nonfunctional at the 2016 Significant number of violations during past several months.	NOD-2018-SP-0001	03/15/2018		
1100000 101100		1105 2010 01 0001	03/ 13/ 2010		
Proceed to NOV	Composite samples are being drawn from the chlorine contact chamber. Sampling needs to be post dechlorination.			NOV-2018-PC-0168	05/18/2018
Proceed to NOV	The flow meter is currently broken and has been since			NOV-2018-PC-0168	05/18/2018
Proceed to NOV	Process control logs have not been submitted as required by			NOV-2018-PC-0048	02/19/2018
Proceed to NOV	the permit and the settlement agreement. D.O. reading from previous ORC's equipment indicated the old aeration basin's DO was 6.0 mg/l.			NOV-2018-PC-0233	07/13/2018
	D.O. reading from previous ORC's equipment indicated the old				
Proceed to NOV	aeration basin's DO was 6.0 mg/l. PC need to be received by 10th. New ORC is doing PC.			NOV-2018-PC-0233	07/13/2018
Dragged to NOV	Moratorium remains in effect. Vacated trailers cannot be			NOV 2019 DC 0222	07/12/2019
Proceed to NOV	New CI contact basin: 4/7 (before solids removal pumping) and 3.5/7 after pumping Old CI contact section: 3/7			NOV-2018-PC-0233	07/13/2018
Proceed to NOV	Sample aliquot volume = 130 ml Sampling needs to take place below de-chlorination.			NOV-2018-PC-0233	07/13/2018
Proceed to NOV	Chart recorder not working.			NOV-2018-PC-0233	07/13/2018
	PC are being performed. They indicate the plant continues to				
	have operational issues, excessive solids. New ASB 30-minute settle ability: 95% Old ASB 30-minute settle ability: 95% Old				
	clarifier/polishing clarifier: 3'/8' (blanket or solids/total depth)				
	New CI contact basin: 4/7 (before solids removal pumping) and				
	3.5/7 after pumping Old Cl contact section: 3/7 Circular clarifier: 8/9 Old clarifier/polishing clarifier: 3'/8' (blanket or				
	solids/total depth) New Cl contact basin: 4/7 (before solids				
	removal pumping) and 3.5/7 after pumping Old Cl contact section: 3/7 Circular clarifier: 8/9 Old clarifier/polishing				
	clarifier: 3'/8' (blanket or solids/total depth) New Cl contact				
	basin: 4/7 (before solids removal pumping) and 3.5/7 after				
Proceed to NOV	Jim Queen, who has been ORC for years Certification has been			NOV-2018-PC-0233	07/13/2018
	revoked. The BORC (Joe David Hall) is to become the ORC. At the time of the inspection the contract between				
	Environmental Inc. and the owner (Mr. Rice) was still in the				
	works. An ORC designation form for the new ORC has not heen submitted. Mr. Queen is still listed as QRC in DWR				
Proceed to NOV	Old clarifier/polishing clarifier: 3'/8' (blanket or solids/total			NOV-2018-PC-0233	07/13/2018
	depth) Circular clarifier: 8/9 Old clarifier/polishing clarifier: 3'/8' (blanket or solids/total				
	depth) Circular clarifier: 8/9				
	Old clarifier/polishing clarifier: 3'/8' (blanket or solids/total				
Proceed to NOV	depth) Circular clarifier: 8'/9' Issues with circular clarifier Solids remain in the contact chamber.			NOV-2018-PC-0233	07/13/2018
Proceed to NOV	Sample location not below all treatment units.			NOV-2018-PC-0233	07/13/2018
No Action, BPJ					
	•				
Proceed to NOV	Chart recorder still not working.			NOV-2018-PC-0233	07/13/2018
Proceed to NOV	Solids remain high through plant.			NOV-2018-PC-0233	07/13/2018
Proceed to NOV	Excessive solids and scum remain.			NOV-2018-PC-0233	07/13/2018
No Action, BPJ	•				

Proceed to NOV	D.O. readings were between 2.87-3.47 mg/l. Settleability was
Trocced to Nov	95%. Structural issues noted at aeration basin and clarifier
Proceed to NOV	iunction. See summary and TA report. Chlorine contact blanket was 1.5'/6'. Structural issues noted at the tablet chlorinator and the clarifier junction.
Proceed to NOV	
Proceed to NOV	Observations and process controls conducted during
Proceed to NOV	inspection indicate solids issues. Structural decay was noted. Blanket levels were 4.5'/7' and 6'/7'. See summary and TA
Proceed to Enforcement	report. The chlorine contact chamber was filled with solids within one foot of the side water depth.
Proceed to Enforcement	The chlorine contact chamber was filled with solids within one foot of the side water depth.
Proceed to Enforcement	Grab sample of effluent for fecal coliform was 530 col/100 ml which exceeds the daily max limit by 32%.
Proceed to Enforcement	Sampling is not being performed after all treatment units.
Proceed to Enforcement	Grab sample of effluent for fecal coliform was 530 col/100 ml which exceeds the daily max limit by 32%.
Proceed to Enforcement	Sampling is not being performed after all treatment units.
Proceed to Enforcement	Clarifier had lots of floating solids on the surface.
Proceed to Enforcement	Clarifier had lots of floating solids on the surface.
Proceed to NOV	At the time of the inspection it was evident that the screening was not adequate, and large debris passed through them
Proceed to NOV	causing downstream treatment unit to not operate properly. At the time of the inspection the drying beds were overgrown with vegetation. Drying beds must be properly maintained.
Proceed to NOV	with vegetation. Drying beds must be properly maintained. The flow meters at each treatment train are connected to a totalizing system (with chart recording). Both flow meters and
Proceed to NOV	totalizing system were overdue for calibration, last calibrated on 7/28/2016 bv Ken Nash Co. Chain of Custodies for field parameters (pH, DO, chlorine and temperature) were not available for review during the
Proceed to Enforcement	inspection. Facility must have all data used for DMR reporting available for review. Effluent grab sample had 22mg/L of BOD. This is 193% in
Proceed to Enforcement	exceedance of the daily max limit. Effluent grab sample had 22mg/L of BOD. This is 193% in
Proceed to Enforcement	exceedance of the daily max limit. Bar screen is rusting out.
Proceed to Enforcement	Facility is overgrown with vegetation. Plant structure is rusting. Holes have rusted through between aerobic digester and aeration basins.
Proceed to Enforcement	Bar screen is rusting out.
Proceed to Enforcement	Facility is overgrown with vegetation. Plant structure is rusting. Holes have rusted through between aerobic digester
Proceed to Enforcement	and aeration basins. The bar screen is rusting away.
Proceed to Enforcement	The bar screen is rusting away.
Proceed to Enforcement	BOD grab sample result was 19 mg/L, which is 153% in exceedance of the daily max limit.
Proceed to Enforcement	BOD grab sample result was 19 mg/L, which is 153% in exceedance of the daily max limit.
Proceed to NOV	The outfall needs to be accessible. The ORC could not locate/access the outfall.
Proceed to NOV	The facility sampler is broken and has been for months according to Vince. A sampler is being brought to the site for composite sample collection, but it is not taken as a flow

NOV-2018-PC-0238	07/16/2018					
NOV-2018-PC-0238	07/16/2018					
NOV-2018-PC-0238	07/16/2018					
NOV-2018-PC-0238	07/16/2018					
NOV-2018-PC-0238	07/16/2018					
		SP-2018-0006	03/05/2018	\$1,750.00	\$113.52	\$1,863.52
NOV-2017-SP-0016	10/20/2017					
	, ,	SP-2018-0006	03/05/2018	\$1,750.00	\$113.52	\$1,863.52
		SP-2018-0006	03/05/2018	\$1,750.00	\$113.52	\$1,863.52
NOV-2017-SP-0016	10/20/2017		35, 55, 2525	<i>+-</i> /	,	7-,
NOV-2017-SP-0016	10/20/2017					
NOV-2017-SP-0016	10/20/2017	SP-2018-0006	03/05/2018	\$1,750.00	\$113.52	\$1,863.52
NOV-2017-PC-0681	10/27/2017					
NOV-2017-PC-0681	10/27/2017					
NOV-2017-PC-0681	10/27/2017					
NOV-2017-PC-0681	10/27/2017					
		PC-2017-0041	10/24/2017	\$200.00	\$113.52	\$313.52
NOV-2017-PC-0518	08/29/2017					
		PC-2017-0041	10/24/2017	\$200.00	\$113.52	\$313.52
		PC-2017-0041	10/24/2017	\$200.00	\$113.52	\$313.52
NOV-2017-PC-0518	08/29/2017					
NOV-2017-PC-0518	08/29/2017					
		SP-2017-0006	11/07/2017	\$150.00	\$113.52	\$263.52
NOV-2017-SP-0015	10/20/2017		, - , -	,	,	,
		SP-2017-0006	11/07/2017	\$150.00	\$113.52	\$263.52
NOV-2017-SP-0015	10/20/2017	3. 2017 0000	11,01,2011	Ψ 1 00.00	Ÿ113.32	4200.32
NOV-2017-3F-0013	10, 20, 2017					
NOV-2018-PC-0171						

Proceed to NOV	Pipe coming from the chlorine contact chamber is slowly			NOV-2018-PC-0171							
Proceed to Enforcemer	nt Effluent pipe was buried and could not be located.					PC-2017-0040	10/24/2017	\$500.00	\$11	13.52	\$613.52
Proceed to Enforcemer	nt Effluent pipe was buried and could not be located.			NOV-2017-PC-0514	08/29/2017						
Proceed to Enforcemer	nt Composite effluent sampling is not being performed as					PC-2017-0040	10/24/2017	\$500.00	\$11	13.52	\$613.52
Proceed to Enforcemen	required by the permit. It Effluent sample should be taken after the aeration chamber					PC-2017-0040	10/24/2017	\$500.00	¢11	12 52	\$613.52
Proceed to Emorcemen	not in it.					PC-2017-0040	10/24/2017	\$500.00	\$1.	13.52	\$015.52
Proceed to Enforcemen	nt Composite effluent sampling is not being performed as			NOV-2017-PC-0514	08/29/2017						
Proceed to Enforcemer	required by the permit. It Effluent sample should be taken after the aeration chamber			NOV-2017-PC-0514	08/29/2017						
Proceed to Enforcemen	not in it. nt Plant is overgrown with vegetation. Trees and vines are					PC-2017-0040	10/24/2017	\$500.00	\$11	13.52	\$613.52
Proceed to Enforcemer	hanging over treatment basins and growing through the fence. at Tanks and protective metal boxes are rusting and need					PC-2017-0040	10/24/2017	\$500.00	\$11	13.52	\$613.52
	protective coatings.						-, ,	,	,		,
Proceed to Enforcemer	nt Plant is overgrown with vegetation. Trees and vines are			NOV-2017-PC-0514	08/29/2017						
Proceed to Enforcemen	hanging over treatment basins and growing through the fence. It Tanks and protective metal boxes are rusting and need			NOV-2017-PC-0514	08/29/2017						
Proceed to Enforcemen	protective coatings. It Effluent pipe is buried and could not be located during the					PC-2017-0049	11/22/2017	\$750.00	\$11	13.52	\$863.52
Proceed to Enforcemen	inspection. It Effluent pipe is buried and could not be located during the			NOV-2017-PC-0671	10/20/2017						
Proceed to Enforcemer	inspection. It Grab samples are being taken for the parameter testing, but					PC-2017-0049	11/22/2017	\$750.00	\$11	13.52	\$863.52
Proceed to Enforcemer	the permit requires composite sampling at this facility. It The ORC is sampling from the chlorine contact chamber rather					PC-2017-0049	11/22/2017	\$750.00	\$11	13.52	\$863.52
Proceed to Enforcemer	than past all treatment units. It Grab samples are being taken for the parameter testing, but			NOV-2017-PC-0671	10/20/2017						
Proceed to Enforcemer	the permit requires composite sampling at this facility. It The ORC is sampling from the chlorine contact chamber rather			NOV-2017-PC-0671	10/20/2017						
Proceed to Enforcemen	than past all treatment units. nt BOD grab sample test result was 13mg/L. This is in					PC-2017-0049	11/22/2017	\$750.00	\$11	13.52	\$863.52
	exceedance of the daily max limit by 73%.			NOV 2017 DC 0674	40/20/2047	. 0 2027 00 10	,,	4 700.00	*	-0.0-	7000.01
Proceed to Enforcemen	nt BOD grab sample test result was 13mg/L. This is in exceedance of the daily max limit by 73%.			NOV-2017-PC-0671	10/20/2017						
Proceed to NOV	Sludge was being disposed of in an unpermitted landfill			NOV-2018-PC-0305	08/14/2018						
Proceed to NOV	Outfall had been moved to an upermitted location.			NOV-2018-PC-0305	08/14/2018						
Proceed to NOV	Mixed liquor was dark with very litte foa, and dissolved oxygen was only 0.48 mg/l.			NOV-2018-PC-0227	07/10/2018						
Proceed to NOV	The composite sampler must be fixed. Temperature indicator			NOV-2018-PC-0227	07/10/2018						
	read 79.8 degrees Celsius during the inspection. Mr. Flynt said that this isn't correct and the temperature indicator/reader										
	must be replaced. It must be replaced so we know that										
Proceed to NOV	samples are being refrigerated to the proper temperature Bar screen is no longer installed. It is believed to have fallen			NOV-2018-PC-0227	07/10/2018						
Proceed to NOV	into the influent pump tank. Cannot see into the tank to assess amount of grease.			NOV-2018-PC-0227	07/10/2018						
Proceed to NOV	Permit not on site. Sludge removal records incomplete.			NOV-2018-PC-0227	07/10/2018						
Proceed to NOV	There are some floating solids. More sludge may need to be			NOV-2018-PC-0227	07/10/2018						
Proceed to NOD	returned or wasted. ORC reported the bar screen is not really in use. Mascerator	NOD-2017-PC-0216	07/28/2017								
	pumps are used to decrease the particle size, and debris is										
No Action, BPJ	pumped as needed, but some buildup of grease and debris ORC reported that extra bulbs are kept at his house (about 10										
	minutes away) due to theft concerns. Likewise, backup										
No Action, BPJ	chlorine tablets are available for use at other plants this ORC ORC uses an infrared thermometer for temperature										
No Action, BPJ	ORC had an old copy of the permit available (current permit										

came into effect June 1, 2017).

Proceed to NOD	Drive unit does not work. Weirs did not appear to be	NOD-2017-PC-0216	07/28/2017							
	completely level - one side appeared about an inch lower than									
	the other. There was some sludge buildup in the center well. There was some algae growth on the outer weirs. According to									
	the ORC, getting the drive unit fixed has not been a priority									
	hecause of prolonged low flow compared to designed flow									
Proceed to NOV	Both blower/motor units were not operational. One of the			NOV-2018-PC-0033	02/20/2018					
	blower/motor units did not have a belt and the second blower/motor unit appeared to be "locked up" Please be									
	advised that the NPDES Permit requires the permittee to									
	properly operate and maintain the facility at all times (Permit									
	Reference: Part II Section C(2) Proper Operation and				/ /					
Proceed to NOV	The aeration basins did not have a properly maintained			NOV-2018-PC-0033	02/20/2018					
	microbial population. One of the blower/motor units did not have a belt and the second blower/motor unit appeared to be									
Proceed to NOV	No dechlorination tablets in the treatment unit were			NOV-2018-PC-0033	02/20/2018					
Proceed to NOV	Access to the discharge outfall was not being properly			NOV-2018-PC-0033	02/20/2018					
Proceed to NOV	One of the influent pumps was not operational (potentially			NOV-2018-PC-0033	02/20/2018					
D 1. NOV	bad switch) .				00/00/0040					
Proceed to NOV	The clarifier drive unit was not operational.			NOV-2018-PC-0033	02/20/2018	DC 2017 0026	00/44/2047	Ć500.00	6446.00	Ć646 02
Proceed to Enforceme	nt The right of way to the outfall was not maintained. A fence had been erected where before there was access to the					PC-2017-0036	09/11/2017	\$500.00	\$116.93	\$616.93
Proceed to Enforceme	nt The right of way to the outfall was not maintained. A fence			NOV-2017-PC-0460	07/13/2017					
	had been erected where before there was access to the									
Proceed to Enforceme	nt Composite sampler is not set up for flow propotional					PC-2017-0036	09/11/2017	\$500.00	\$116.93	\$616.93
	sampling. Effluent meter needs to be wired into sampler.									
	Attempt at drawing 10ml aliquot resulted in about 700-1000 ml draw. Attempt at 100ml draw resulted in an aliquot of									
Proceed to Enforceme	nt Composite sampler is not set up for flow propotional			NOV-2017-PC-0460	07/13/2017					
	sampling. Effluent meter needs to be wired into sampler.									
	Attempt at drawing 10ml aliquot resulted in about 700-1000									
Proceed to NOD	ml draw. Attempt at 100ml draw resulted in an aliquot of Facility does not hold a field certication for pH nor	NOD-2017-PC-0268	12/21/2017							
Proceed to NOD	No apporved temperature measuring device in effluent	NOD-2017-PC-0268	12/21/2017							
	compostie sampler									
Proceed to NOD	Temperature verification calibration records were not	NOD-2017-PC-0268	12/21/2017							
Proceed to NOV	available for review. Unpermitted discharge of wastewater observed entering			NOV-2018-PC-0064	02/20/2018					
	stormwater drainage system at centralized wastewater				02, 20, 2020					
	disposal station for airplanes.									
Proceed to NOV	pH analyses not performed within required holding time			NOV-2018-PC-0064	02/20/2018					
	during 4 quarterly sampling events at all Stormwater Outfalls in 2017. DO and pH analyses not performed within required									
	holding times during January and March 2017 de-icing									
	sampling events at Outfalls 002 and 004.									
Proceed to NOV	No flow reported at Outfall 001 in August 2017. No effluent			NOV-2018-PC-0064	02/20/2018					
	monitoring performed at Outfall 001 in September 2017.No ORC visitation and operation/maintenance records available									
	for August and September 2017 (except last week of									
Proceed to NOD	Chlorine Contact Tank: Moderate amount of floating	NOD-2018-PC-0028								
D 11 NOD	solids/scum were observed.	NOD 2040 DC 0020								
Proceed to NOD	DWR BOD result exceeded the limit. The ORC's lab (Environmental Inc.) results were compliant.	NOD-2018-PC-0028								
No Action, BPJ	(Environmental Inc.) results were compliant.									
Proceed to NOD	Appeared clogged. Floating foam/scum was apparent. File	NOD-2018-PC-0028								
	review indicates media was replace ~6 years ago. This system									
N. A. /	needs to be evaluated to determine if it is properly operating.									
No Action, BPJ	. Callura to calibrate flavores services devices across the	NOD 2040 BC 0044	02/02/2040							
Proceed to NOD	Failure to calibrate flow measuring device annually.	NOD-2018-PC-0014	02/02/2018							
Proceed to NOD	Failure to mointor flow continously.	NOD-2018-PC-0014	02/02/2018							

Proceed to NOD	Failure to calibrate field meters annualy.	NOD-2018-PC-0014	02/02/2018		
Proceed to NOD	Failure to perform and document daily post calibrations as applicable.	NOD-2018-PC-0014	02/02/2018		
Proceed to NOD	Excessive vegetation and ponding observed on sand filter.	NOD-2018-PC-0014	02/02/2018		
Proceed to NOD	Failure to perform adequate maintenance. Sluge removal records were not availabe for review.	NOD-2018-PC-0014	02/02/2018		
Proceed to NOV	Treatment unit (carbon filter) was bypassed at the time of			NOV-2018-PC-0008	01/16/2018
Proceed to NOV	inspection. Bypass was not reported to the Division as required by the			NOV-2018-PC-0008	01/16/2018
Proceed to NOD	Neither the ORC or BORC(s) have been officially desginated.	NOD-2018-PC-0211	07/11/2018	NOV-2016-PC-0006	01/16/2016
Proceed to NOD	None	NOD-2018-PC-0211	07/11/2018		
Proceed to NOV	The effluent sampling is not flow proportional as required by	1100 2010 1 6 0211	07/11/2010	NOV-2017-PC-0604	09/11/2017
	the permit.				,,
Proceed to NOD	There are no records avaiable to indicate the flow meter has been calibrated within the past year.				
No Action, BPJ	O&M records were reviewed during the site visit. The records				
	included flow measurement recordings. The records indicated				
	the air stripper had been cleaned within the last year.				
	Currently, three of the ten recovery well are not in service. RW-6 has extensive roots growing into the well gallery that				
Proceed to NOV	Sampling has not been condcuted as required by the permit.			NOV-2017-PC-0642	
	Samples were taken as follows: May & December 2013,				
Duran de NOD	September 2014, May 2015, and August 2017.	NOD 2017 DC 0267	42/40/2047		
Proceed to NOD	Missing monitoring reports and parameters.	NOD-2017-PC-0267	12/19/2017		
Proceed to NOV	ORC must contact MRO staff in case of a violation within 24			NOV-2018-PC-0125	04/12/2018
	hours from the time he becomes aware of the violation.				
Proceed to NOV	Effluent location was not identified at the time of the			NOV-2017-PC-0693	11/07/2017
Proceed to NOV	inspection. facility staff must find the discharge location of No sampling recordes were avilable for review at the time of			NOV-2017-PC-0693	11/07/2017
	the inspection.				,,
Proceed to NOD	Facility has reported 11-Total Residual Chlorine violations from	NOD-2018-PC-0012	01/29/2018		
Proceed to NOV	12/19/2014 thorugh 09/08/2017 Effluent is combined with storm water. Combined effluent at			NOV-2017-PC-0641	10/05/2017
TIOCEEU LO NOV	the drainage ditch was observed and to be black in color.			NO V-2017-FC-0041	10/03/201/
	Retention pond was observed to be black.				
Proceed to NOV	PH and Temperature of Bi-annually on-site sampling were			NOV-2017-PC-0641	10/05/2017
	recorded and were readily available for review. No Flow				
Proceed to NOV	measurements were recorded The permittee monitors flow and pH, but also required to			NOV-2017-PC-0601	
-	monitor temperature and Chemical Oxygen Demand at least				
	semi-annually to comply with the monitoring requirements in				07/05/55:-
Proceed to NOV	Slightly turbid and odorous effluent / TSS exceedance likely due to needed maintenance to filters.			NOV-2018-PC-0209	07/02/2018
Proceed to NOD	No sampling has been conducted since 2010.	NOD-2017-PC-0227	08/31/2017		
			. ·		
Proceed to NOV	System is failing.			NOV-2017-PC-0612	09/20/2017
Proceed to NOV	Sand filter reportedly undersized and clogged. Sewage			NOV-2017-PC-0612	09/20/2017
Proceed to NOV	surfacing and runoff. Failure to properly operate and maintain the disinfection unit.			NOV-2018-PC-0028	
Proceed to NOD	The washing machin does not appear to be connected to the	NOD-2018-PC-0204	06/29/2018	1.01 2010 1 0 0020	
	treatment system and is discharging at the front of the house.		,,		
Proceed to NOV	Lack of disinfection			NOV-2018-PC-0089	03/20/2018
Proceed to NOV	Solids observed around the discharge point			NOV-2018-PC-0089	03/20/2018
rioceed to NOV	Somes observed around the discharge point			1101-5010-50-0093	03/20/2018
Proceed to NOV	All tanks were full and pump tank was seeping			NOV-2017-PC-0639	10/11/2017
a li nei				NOV 2017 RG 2022	40/44/224=
Proceed to NOV	Failure to maintain the system			NOV-2017-PC-0639	10/11/2017

Proceed to NOV	Failure to sample	NOV-2017-PC-0639	10/11/2017
Proceed to NOV	No disinfection provided at the time of inspection.	NOV-2017-PC-0722	12/29/2017
Proceed to NOV	A visual review of the outfall location shall be executed twice each year (one at the time of sampling) to ensure that no	NOV-2017-PC-0683	11/08/2017
Proceed to NOV	visible solids or other obvious evidence of svstem Facility discharging black, odorus wastewater.	NOV-2017-PC-0683	11/08/2017
Proceed to NOV	treatment system shall be maintained to prevent seepage of	NOV-2017-PC-0683	11/08/2017
Proceed to NOV	sewage to surface or ground water. The Permittee shall at all times properly operate and maintain all facilities and systems of treatment and control (and related appurtenances) which are installed or used by the Permittee	NOV-2017-PC-0683	11/08/2017
Proceed to NOV	to achieve compliance with this condition of the permit. Failure to properly maintain the treatment system and all	NOV-2018-PC-0018	
Proceed to NOV	system components at all times. UV damaged / not operating.	NOV-2017-PC-0719	12/29/2017
Proceed to NOV	failure to operate and maintain waste treatment system	NOV-2017-1 C-0719	06/05/2018
Proceed to NOV	Septic tank needs to be pumped. Annual samples need to be	NOV-2018-PC-0050	02/19/2018
1100000 10 110 1	completed	1101 2010 1 0 0000	02,13,2010
Proceed to NOV	annual samples needed	NOV-2018-PC-0050	02/19/2018
Proceed to NOV	outfall covered in sediment	NOV-2018-PC-0050	02/19/2018
Proceed to NOV	need new chlorine and dechlor tablets	NOV-2018-PC-0050	02/19/2018
Proceed to NOV	Pump station stays in alarm.	NOV-2018-PC-0050	02/19/2018
Proceed to NOV	Pump the septic tank	NOV-2018-PC-0050	02/19/2018
Proceed to NOV	The subject permit requires annual acute toxicity 24-hour composite sample and grab samples. At the time of the inspections it was discovered the facility has failed conduct composite sampling, and do not have the proper equipment to conduct such sampling. ORC was instructed how to preform	NOV-2018-PC-0123	04/12/2018
Proceed to NOV	DMRs, chain-of-custody's (COCs), and calibration logs from June 2017 through February 2018 were reviewed for the inspection. At the time of the inspection it was determined that COCs do not include the name of individual relinquishing	NOV-2018-PC-0123	04/12/2018

PENALTY DWR REMISSION DWR REMISSION EMC REMISSION EMC REMISSION OAH PETITION OAH REMISSION SUP COURT CASE SETTLEMENT CASE TOTAL PAID BALANCE CASE CLOSED **WAIVED AMT** REMISSION DATE REMISSION AMT SETTLEMENT DATE DATE AMT DATE AMT DATE **AMT** DATE DUE AMT

\$1,876.81 \$0.00 11/17/2017

\$1,876.81 \$0.00 11/17/2017

\$1,876.81 \$0.00 11/17/2017

\$226.81 \$0.00 11/16/2017

			\$1,876.81	\$0.00	11/17/2017
1	1/07/2017	\$0.00	\$4,510.31	\$0.00	12/08/2017
1	1/07/2017	\$0.00	\$4,510.31	\$0.00	12/08/2017
1	.1/07/2017	\$0.00	\$4,510.31	\$0.00	12/08/2017
4	1/07/2017	¢0.00	Ć4 F40 24	ćo 00	42/09/2047
1	1/07/2017	\$0.00	\$4,510.31	\$0.00	12/08/2017

04,	/05/2018	\$0.00	\$3,209.77
04,	/05/2018	\$0.00	\$3,209.77

03/02/2018 \$2,700.00 \$11,403.26

\$1,863.52

\$1,863.52

\$1,863.52

\$1,863.52

\$313.52

\$313.52

\$313.52

\$263.52

\$263.52

\$613.52 \$613.52 \$613.52 \$613.52 \$863.52 \$863.52 \$863.52

\$616.93

\$616.93